10-5-1963 Set C/M over rod or Conc cylinder.
mons. Could be broken off. RB.

#751005

section corner 9-10-15-16 Kalmar 107-15

11-1887 Hunter P422 no. 411 S10 F Kompbell.
found old stake in ground tieted stumps A B trees
set quarry stone with new stake by side.
– meas north 39.94. to stake set this survey from old
line east from center over 1/16 cor west.
– east set stake at. 11.63½ chen. 6.00 chen 7.41 chen 14.96½
Complicated property survey S W 1/4 10.

---

corner found by McGhie or other surveyor & maintained
Set C/M as corner 10-1963.
– meas north 2633.5 to W 1/4 10.

(over)

there is a 1/2" rod in place 11-5-75
on section line 9-10 as 1/64 corner in
road south & 1/4 9-10 658.37' south it lies about
6' north edge of traveled road surface or
• 5' west and ~~18.6 south~~ & to bottle cap in tele pole = (gone 11-7-75

RP to sec cor 9-10-15-16. — 11-7-1975 Co. Surv.

~~fence corner~~ fe. Cor. post now on E. side of mon. ±6" ~~north 4.0~~

Sp 24" maple - O.K. west 25.4.

~~Lath~~ 30" elm NE ~~21.6~~ 21.10

Spike in N.W. side of

Gov't Mons Karrick 1857

80.00 sec corner scribed post in

Asphalt 12 S 51 W 12

Maple 20 N 52 W 73

Asphalt 12 N 67 E 85

" " 14 S 63 E 22