X 6-7-76 Set CIM #751406 ①

1/4 Corner 14-15 Kalmar 107-15

3-1873 Hunter P217 No 221 S15 J Fairchild, C Finn.

Corner missing, ground froze did not establish corner.

- 1/16 west run N-S 1/16 line from N line 15 to S line 15 set only line & 1/16 west not the working & southing.. all done by chainage only. only 1/16 on north line which was done by M&L. 19.94 1/2 from NE 15. - South line of SE 1/4 15 } 19.97 1/2 M&L Ave. M+L From Cor. 15 To E.1/4 = 19.96

caption dated 10-29-1879. set this corner a stone likely as "stone by Hunter" refered to later by projecting line from E 1/4 14 over Center 14 intersecting west line 15

- meas north 39.87 - south 40.29

263642 2659.14 (per)

4- 1892 2 Lns Fraser P 482 No 457 S 14-11 Chas Foster.
found stone set by Hunter. likely 10-1879.
T.F. field Book 8 P. 21 - fd squared Limestone as 1/4 p. W. side 14
- meas north 39.83 2628.78
bearing of courses at NE 15 S 12° E - N 89 3/4 W.

1924 Co H.D B39 P78 found stone at 1/16 corner east Hub R Ps. 50' NE & NW.

5-8-1968 J Kerr. set section corners N & L (Note Co H.D 1927 B51 P71. Calls for stone and spike in slag. 3 hub R.P.S. See #2 card
meas line 5285.45.
set corner on prog meas of survey 10-1879.
- meas south 2657.05. to C/M S W 14. R. 2659.15'
- meas north 2628.4. to C/M. N W 14. R. 2631.4.
1/16 south set 120 D M & L. 1328.54 3' south and 5 1/2' E corner post of 3 way fence. corner. no south fence.
- as 1/4 corner set 1/2" rod. came near & black top road
13' east of fence line south. - 16.7 to Center Number plate 21517 south side band under plate No E15-14-10.0-1.5 pole NE

6-7-76 Set CIM

#751406

Card # 2. 1/4 14-15 Kalmar 107-15

(2)

1927. Co HD B51 P71.
found stone and spike in place -
Hub SW on E-W fence line 50.2.
Hub SW near 4th fence post 69.4.
Hub SE on E-W. fence line 50.2.

-16 corner each 1/4-14-15. SE cor west 1/2 NW 1/4 14.
found stone in place. - B 51 P73.
hub NW on fence line west 50.0.
hub NW near 4th fence post No 43.8.
hub NE on fence line North 50.9

6-3-76 Dug 3'x3'x6' (5ft Rock) x 9½' deep with backhoe at Ken's rod often measuring the E line of Section 15 and measuring W. to 1/16 fence. $ Diggings to cover protected T.H. measure (N-S) and T.H. measure to 1/16 W. Area had previously been dig. Found nothing.

6-7-76 Set CIM over 1"x12" pipe on line and at prorated T.H. measure .2 S and appro. .05 W (Top of Kerr rod bent E) of Kerr rod (removed).
Fence S. mor-gone. CIM ½' S of ℄.
R.P.'s CSD in pp#21518 NW 199.1
CSD in pp#21517 NE 116.9s
Govt Notes Kamack 1954
40.00 Set ¼ cor. post in mound with found pipe, charred stake & Osage Orange scribed NE & S.W.

"751406" E 5-21-98 MW EA 39

✓1/4 Cor 14-15 107-15 Kalmar
Fd CIM 11½" deep in blacktop
CR#4 we will not remove
will set 12" pipe w/cap after
Resurfacing
Set Ref. pipe w/cap on North
backslope CR#4 48' North
of ℄

T℄ Refpipe
RT P.K. nail in P.P. # 21517
(1st pole East) to 1/4 Cor 14-15
73°47 09 dhos 75°17'30" dho4
0°07'18" dho3 1°37 43 dho1
73°39'51" 73°39'47 Δ=73°39'49"

To 1/4 Cor 14-15
VA 85°01'21" dV06
Slope 48.62 Hor 48.435

6-9-99
EPA MAC MR

"751406" 1/4 14-15 107-15 73
FOUND PK NAIL SET BY SURVEY CREW @ SURFACE
SET 1" SQ PIPE W/CAP AS FINAL CORNER.
CORNER FALLS 1 1/2' S OF CR 14 + 175 1/2' E
OF ℄ FARM DR S.
CSD IN PP # 21517 ENE 116.92'