#751506

1/4 Corner 15-16 Kalmar 107-15

Govt Works Karnick 1954

16.00 S of 1/4 S of post in mound w/ brush, pits, charred stake and Orange Orange seeds WE 1 S.W.

4-11-1973 Survey Drawing for Daly Property Shows Fd. 3/4" pipe on E B.t. road in line of Fence South. (Assumed 1/4 Corner)

Note: 5-26-98 This Corner used for many Surveys & referenced before Cold recycling of Black top C.R. # 4

"751906" B 5-21-98

✓1/4 Cor 15-16 107-15 Kalmar
Fd pipe 4" deep in ℄ CR #4
Set Ref pipe w/Cap on East Edge field Drive North
℄ CR #4 South 44 1/2'
℄ field Drive west 12'

TC@ Ref pipe
Art P.K. Nail in PP# 21958 (pole South of Corner) to 1/4 Cor 15-16

347° 55' 19" dh 01 | 349° 09' 41" dh 00
0° 03' 00" dh 00 | 1° 17' 14" dh 01
347° 52' 19" | 347° 52' 27"

To 1/4 Cor 15-16
VA 90° 01' 06" dv 03
slope 281.68 Hor 281.68

"751506" 1/4 COR 15-16 107-15 6-9-99 EA MC MR

FOUND PK NAIL SET BY SURVEY CREW @ SURFACE

SET 1" SQ PIPE W/CAP AS FINAL CORNER

CORNER FALLS IN ℄ CR #4

CSO IN FENCE COR POST S 50.22'