1 - 12-4-70 set 3/8" x 3½' reinf rod M & L 2627.3 (1)

12-11-76 Fd ⅝" rod cup ½ foot by K. Ewers

3-9-77 Set CTC #751706

¼ Corner 17-18 Kalmar 107-15

Belgine this survey in Orion Co. -1977

4-1905 Robt Fraser P82B SE ¼ 18 W Mochnke & ally.

found stake with iron by side which came on south side of road and 10 lks or more west of fence, set in previous survey M & L by R Fraser. Meas west came within ½ lks of previous survey. below 19.78 ½ this survey. (305.81

Robt Fraser set stake & iron prev surv. S. 2638.6. this survey.

1-1893 W Fraser P503 no 473 S 18 road line - town board found 1/16 stake between center (stake found undisputed) and east ¼ 18 to be M & L. 19.80 ½ set in previous unrecorded survey.

(over)

Co Hwy Dept. B84. P74.

assumed corner. run line NW 17 south 5264.4
iron stake NW 17. (stake) limestone at SW 17. set 1x2x18 hub N T L.
2632.2. – fence post SW 64.9 – stump SE 34.7

B84 P20 - ℄ crosses west line ℄17 at Sta 147+72.7
meas north to 1/4 17-18 (not described 598.2
RP to nail ℄ sp bte P 55.3 SSE Hub W 14.0

7-8-70 Co surv ran & meas from ℄ NW cor 17 north on random
set nail ℄ blocking 2031.33 - set nail at 2628.45 Co 2632.2
dug entire area 8' x 20' west ℄ tree row & fence. found nothing positive no iron

11-18-70 cent line north to NW cor 17
found total 5254.6 came 54.36 west ℄ corner including 6' ⓔ E.
which moved chain line east ℄ fence a little.

see Card #2

Card #2 1/4 17-18 Kalmar 10-7-15 (2)
#751706

12-7-70 dug entire area east of fence from 2' both sides of direct line, found nothing at all. Terrain could be river fill or wash - set 3/8" x 3½ rod M & L 2627.3 and 27.18 east of random bringing corner 2'+ east of tree and fence line

7-10-70 dug extensively with tractor for center 17, found massive rock fill deep. found evidence from digging & testimony of Mr Caulfield that entire road bed was washed out for many rods N & S in times past. - run line from nail 2625 North of 1/4 17-20 as found 4' deep west set points at 1234.55 - 1897.85

12-7-70 ran line from 1/4 17-18 as set M & L east over nail set in tree root 1391.88 east of corner which came 6.57S & nail set 2634 North of 1/4 17-20 Cont line east

12-9-70 Completed line 2625.65 from nail at Center 17-6.57 S of orig 2634.4 nail from 1/4 17-20 referenced and found (set 7-7) line came 1.3 south of 1/4 16/17 making 5.92 from Center or 2628.48 south to 1/4 17-20 R 2626.14 see below. over 2.34 north to 1/4 8-17 2617.31 R 2624.16 under 6.85 - Center and 1/4 17-18 should both go south. R Fraser meas of 2638.6 supposedly set M&L must be in error being 2638.6 - 2627.3 or 11.3 from present M&L. If corner is 8' south yet to appraise fit line east

- dug east of tree row where M&L came, from 2' south to 6' north and E&W as trees would allow at least 3' east of tree fence row, should have dug further south. - on line from W 1/4 18 east found 5/8" rod up 10" ± 29.63 south of 3/8" rod set as 1/4 17-18 M&L 2627.3 and 3.37 W of rod 1/4.

4-19-91 dug again south and west of M&L found nothing accepted rod set M&L as true corner (final) line east to 1/4 16-17 paralleled fence east of center so well made it look even better. will make Center 1.3 south now S. 2628.48 R 2626.14
2634.4 - 6.57 (Random ⑤) + .65 (1/2 1.3) = 2628.48 (a further OK check.

1/4 Corner 17-18 Kalmar 107-15 (3)
#751706

3-9-1977 Accepted 3/8" rod set M&L in 1970 by the County Surveyor. Drove a C.I.C/24" P² over the 3/8" rod. Corner 2½' East of old fence line N-S

R.P.'s Spike and CSD in East side blazed 11"
Box Elder SSW 7.35'

Spike and CSD in West side of blazed 12"
Box Elder NNW 7.75'

4-16-1986 RWB Found Monument
Top monu. near flush with ground surface
it is ± 60' North of Corner of Tree rows N & E
Above ties O.K. but starting to grow over

#751706 | 4

¼ cor. 17-18 Kalmar 107-15

K.P.'s 1976 to rod fd. by K. Ewers

18" Ash S 5 E 15.0'
Ctr clump of 7 (10" Ash) S.W. 19.0
8" Bore Her (with 4" sprout) N 8.0'
Old fence row N. + East

These Ties No good 4-16-86 RLB

Govt Mkrs Karrick 185'

40.00 set ¼ set post in mound with trench, pits, charred stake + Orange Surv Ribbon