1 8-2-71 set CIM over 3/4 x 13" iron #751709 (1)

2.

1/4 · corner. Center 17 Kalmar 107-15.

1-1870 Perry. P94 no 138 & 17. Sinclair.
found corner as set in 1869. by Perry.
18" elm. N 37°10E 1.76 chs.
- 1/16 north set stake 19.88 M & L. (1312.08'
4" burr oak N 80½°E 1.33 tree marked 1/4 cor
12" cottonwood N 31¾°W 2.18 " " "
- 1/16 center NW 1/4 17. found stake 19.85 west of 1/16 cor east.
- also found stake north of above 1/16 chs center NW 1/4 17.
with B tree 10" burr oak N 38°15E 16 lks set 1869.
a 1/64 corner.

(over)

6-1885 Hunter P 397 No 389 S17. D L King etab.
found corner set in sub-division P94 by Perry.
also found BT 18" elm N 37°10 E 1,76 lks. from which
was found standing.
planted quarry ~~stone~~ with slabs by side in place slabs found.
1/16 east - 1/16 on plat M & L 19,94. 1316.04
1/16 south set stone center road. M & L 19,89½. to stone found
1313.07.

6-29-70 Co surv. meas north from 1/4 17-20 set nail in line of fence
west and 62.5 from center oak tree RP as .00 errored in that set
Nail at 1317.0 (not 1313.07) came well north center road curves some
cont to 2634 (not 2626.14) came 8 or 9' north of field ends east. No
fence only ends of field. RPS Orange Cap in N S PP 40326 WNW 34.93
Rber cap in 4" old cedar post SE side SW 45.75 - 3' W & road slightly
curving around river - 7-6-70 found 1/4 17-20. .4' south of 00 nail
used old nail as Tail of traverse on card #2, set nail 9.0' south as corner
temp

#751709 (2)

Card # 2 Center 17 Kalmar

7-7-70 Co surv. ran careful Traverse, co-ordinate line from nail set 6-29-70 on bearing from true 1/4 17-20 found 7-6-70. Created 5 PIs. all replaced with iron pins and referenced ending directly on iron pipe set by Mc Ghie as 1/4 8-17 N 26 11.39 E 4 of pipe 2.8

7-9-70 ran line west from nail 9' south of 2626.4 from S 1/4 17 set points at 537.95 - 1234.55 (in tree root) 1897.85, 2178.97. Came out .5' S of iron as 1/4 17-18 at 2635.35, this corner can only be proven by completing line N. to N W cor 17.

7-10-70 dug hole 10'+ by 5'4 6' deep in place, awful mess below. Corner could hardly survive unless very deep set. will have to continue line east to C I M at E 1/4 17 solid woods & hills & brush.

12-70 Completed line and set 1/4 17-18 M & L 2627.3 & 2626.43 west of nail set 9' south of orig 2634.4 nail.

12-7-70 started complete E-W 1/4 line proj line from 1/4 17-18 as set M & L

used nail in tree root set at 1237.55 now ~~1391.68~~ 1392.2 east of true M & L 1/4 17-18. - line came 6.57' S of nail still in place at 2634.4 Cont line east - set nail at 1360.0 on 2' ⑤ N.
- Cont line to 1719.37 nail on 10' ⑤ N - set nail 30' N now 40' ⑤ N.
- cont line to 2625.65 exact opp C.J.M. (untied name) came 38.71 N.
- if W 1/4 17 accepted point at center would go 1/2 of 1.29 north or .64 ±
- 6.57 - .64 or 5.93 south of 2634.4 or 2628.47 to S 1/4 17. R 2626.14 Hunter.
- On traverse got 2611.4 to N 1/4 pipe from 2634.4 or 2617.33 R 2624.16 (old survey)

Center 17 & W 1/4 17 could still be further south.

4-19-71. checked mear from small iron at 1/4 17-18 east
mear line carefully from small rod at 1/4 17-18, set M & L 2627.3
- set nail at 1320.0 and small rod at 1353.0 -

Cont east to nail set .65' N of random. 2626.8 + 1.55 that nail lies too far west. 1.4' + .18 or 2628.85 - W 1/4 to true center.
accepted M & L at W 1/4 17 as true corner.
If .65' nail can be found set corner 1.55 E of it for center 17

#751709 (3)

Card # 3 Center 17. Kalmar.

8-2-71. Co surv. found nail set at 2634.4 from 1/4 17-20.
- found nail set. south 6.02 and .15 west above nail.
- Set C1M over 3/4" x 13 1/2 reinf rod as corner
5.93 S and 1.55 E of 2634.4 nail.
- rusty root beer cap on SE side 4" cedar post SW 42.78
2nd post from corner post.
- paper cap in 2nd post west from cor post N side W 48.4.
- Orange cap in N side power pole # 40326. NW 38.88.
corner lies fairly well in Center main road south
very near where road starts to curve.
- corner in line with new Co. park fence.
Meas. E to C1M 1/4 cor. 2624.25 N to 1/4 8-17 2617.33
W to rod 1/4 17-18. 2628.85 S to 1/4 17-20 2628.47