8-18-1964 set CIM over 1"x24" stub #751805 (1)

section corner. West 18-19 Kalmar 107-15

6-1895 H Fraser P578 no 528 S 19 Dodge Co.
found stake set by D. County Surveyor J Kendall.
tested stumps & all 4 B trees - proved correct. F. Pendegast.
set stone 3'x8'x30" as corner.
-1/16 east set stone 5x5x18 on line at 18.71 then 1234.86
19.83 to N 1/4 19. a stone 4x10x18" set this survey
1308.78 2543.64

12-1900 H Fraser P702 no 617 SW 1/4 18 H. Allen
found stone set P578.
-1/16 east found corner set P578.
-east set stake at 2.77 1/4 - then stake 4.06 1/4 then
(192.05) (268.15) = (460.20) over)

stone at 5.08 then 6.79 to 1/16 corner described above
(335.28) (448.14) all for lines north.
795.48 1243.62.

Corner maintained steel post deep by corner.
9-1964 J Kerr L19 for barn board.
found corner set CIM. over 1"x24" rod. with shattered
piece of orig stone by mon. 12-15-70 found CIM
broken in half.

Center 20" basswood.	NE	6.3
" 20" red oak	SW	9.5
steel fence post	N	0.8

7-7-72 Cast Iron Monu. Replaced. after found broken in 1970
Meas East see 1/4 18-19

Gov't Notes Kalmar 1854 1/4 cor. West 18-17 [2]
Kalmar 107-15 #751805

Set corner post to 13, 18, 17, 24

Bur Oak 16 S 27° W 61 links
Black Oak 18 N 35° W 47 " "
Black Oak 16 N 45° E 59 " "
Black Oak 18 S 40° E 60 " "