/ 3-11-81 Reset 5/8" rod & cap from References
12-4-82 set 1"sq post/cap
#752004 ①

1/4 corner 20-29 Kalmar 107-15

5-1871 Perry P162 No 185 L29-30-31-32
found stone monument

9-1933 J Kerr. B 9 P3 L29. Whitcomb.
shows stone on plat in record book at midway 2630.35
between stones.

1937. Co H D B 84 P 2. square iron nail. RPS. marked on top
P12 B84 explains corner. found L stone 8x8 1' E & Cor post at NW29.
found L stone 8x8 by 65' S & E cor under N-S fence
Meas. between 52583 set square nail N & L. 2629.15
-2633.3 S to Calc 29- then 2638.0 To S 1/4 29. (over)

Tues 9-1936 PP NE 65.2, PP SE 36.0, FP W 32.0

1936 Bla 52+71.3 a PI R 0°34' going N.
top B84P34 above fence line west 52+71
fence west going L 28' N 25'

8-21-1974 Co. Surv.

Run line Cen. 20 — N¼Cor. 20 To This Corner.
line fell 1.52' West of 5/8" rod - used as Corner.
Dug hole with Jackhammer down To clean clay and found
Nothing (2'E-W x 4'N-S hole - 3'deep.) Remved 5/8" rod
Set by Others and set 5/8"x12" rod on line from North
and opposite rod which we removed.

SSD in PP WSW 25.04.

Govt Works Kerr-McKee 1954
40.00 Set temp ¼ steel
West on true line between stks 20+29 N 9° 27'
40.00 Set ¼ steel pipe in mound with brush
p. 115. chained stake 1 Orange Orange stake RE P.S.W.

(2)

1/4 Corner 20-29 Kalmar 107-15

#752004

5-13-1980 Took RP's to rod before road grading. Drove iron with cap 78.31 West (as plat corner) on the section line and an iron with cap 178.31 West on the section line. Set a survey marker sign 1/2' West of the ~~road~~ rod 178.31 West of the corner

3-12-81 (1981 Remon Book) Drove 5/8" rod and cap from the reference set prior to road grading

12-4-82, 1/4 Cor 20-29: Set a 6" long 1" sq. pipe/cap on line from iron/cap set 178.31 West and iron/cap (R/W Mon) set 78.31 West (both of Sec. line West) on 5-13-1980 Cored 78.31 East of said R/W monument. Corner set in new concrete on C/L 5', 3.4' West of ℄. Checked location correct with tie of 63.29 to R/W Mon on Sec. line East.