10-31-1964 set C I M over 5/8" x 14" rod. ①

#752006

¼ corner 19-20 Kalmar 107-15.

6-1895 W Fraser P 578 no 528 L19 J Kendall, F Pendergast.

Corner gone, in road cut, on aver of Mr. D T Tompkins set temp stake in line fence south and 2 rods north of willow row south side of road, both set by orig stake.

4-1911 Ch. Larson P 152B L20 for Christian Jensen.

"found" corner.

10-1964. J Kerr L19 town board.

run N-S section line set M & L. 2632.8

(over)

after grading set C/M over 5/8"x14" rod. from.
transit tie To rod 50' south over rod some 60' further S.
just north of oak tree base.

Center 18" oak tree	S	58.0
Disc tab pole.	SW	51.2.
punched cross in W end field culv	NE	49.78.
fence running south.	E	4.0

May, 1874 T. Hunter Book 3 P. 101-102
at "D" found old stub of stake & also stone set by Perry from B.T.s one of which the S.E. is still standing, also found blazed Tree about on line of stone North, Dist of Stone from S.E. B.T. is 192

3-1979 Ron Olson, (Zenk Engr.) called to report that 1/4 line from Sec 20 came 3' South of this 1/4 Corner - used info memo for his Survey

#752006 12

Kalmar 1/4 corner 19-20
Cut 2 Oaks Marked -S Y
10.00 set 1/4 steel post
Bur Oak 10 S 77 W 1.45
" " 17 S 24 E 1.75