9-25-1964 set C/N over stone, corner up 6" #752009 (1)
3-11-81 Reset 1" square w/cap from references
1/4 Corner Center 20 Kalmar 107-15.
5-1874 Hunter P 253 No 253 L 20 W Hamilton, N Stones.
found stone near corner of fence set by Perry
Corner accepted and undisputed.
-1/16 east set stake M & L 19.90.
-1/16 north set stone 2x6x18 M & L. 20.00.
-1/16 center NE 1/4 20 set stake M & L 20.02 on N-S 1/16 line.

4-1911 Chas Larson P152B L 20 E Jensen.
found limestone 4x16x20
-1/16 east found fence corner at 19.90 recorded meas.
-1/16 north set limestone 3x14x18. M & L 20.00.
-1/16 center NE 1/4 20 set boiler flue at 19.98 N of 1/16 east of Center

Co Hwy Dept. B 84 found stone used in road layout.
— 1/16 North found boulder 4 X 8 X 12 - RP oak tree NE 45.0'
— Meas Center 20 south 2639.4 (Co Hwy Dept)

9-1964 J Kerr & 1980 town board
found stone set C I M on top sticks up 6" stone must be lowered or removed.
-RP sickle guard driven into east side
of 30" Cottonwood up 6.0' N 20° W 77.9.
cross cut in north end of east abutment of
bridge on county road no 5 L 85° W 77.07.
5-19-1980 Took RP's before road grading: Set a ½" rod 59.94 East and on line to the head of a Railroad spike driven in the West side of a large Box Elder tree 162.67 East of the corner. The ½" rod is 2' South of a wood fence post with survey marker sign.
6-2-1980 Removed CIM.

(2)

1/4 Corner Center 20 Kalmar 107-15
#752009

3-11-1981 (1981 Remon. BK) Drove a 1" x 35" sq pipe w/cap from reference set for road grading. Corner falls on the southeast corner of the apron to a large concrete culvert. Left construction reference and took one more reference.

Punched cross in the end of a large U Bolt that holds the concrete culvert section together NW 15.89