#752106 (1)

8-27-1965 set C/M one ½" x 17" pipe.
6-9-1976 dug with Tractor & found nothing else, old road was dark to clay accepted above corner now, as correct.

¼ Corner 20-21 Kalmar T 07-15E

5-1872 Hunter P194 No 207 S21 S. Simonson, Rickert

Corner gone. set temp stake M & L 39.90.

5-1874 Hunter P253 No 253 S 20 W Hamilton, N Groves.

set new marked stake in place of temp stake set P197.

– 1/16 west set stake M & L 19.90.

– 1/16 center NE 1/4 20 set stake M & L 20.02 on N-S 1/16 line

---

6-1876 Hunter P296 No 291 S 21 J Murry; W Caulfield

found stake set P 253

– 1/16 south set stake M & L. 19.97 ¾ – Caption. set stone here in survey 10-20-1886 Corner


– south ¼ above 1/16 corner. set stone 5x6x17. N & L
9.98 3/4. To L W. 21. (found this stone 1965)
= 659.18

4-1911 Chas Larson P 152 B. L 20 C Jensen
didn't find corner, used fence line east, didn't look likely.
1/16 west used fence corner as 1/16 corner

8-1965 J Kerr BOOK 90 P. 46 L 21 Sewert Thompson.
didn't dig for stake. dug fill. found stones at both N & S sec corners. dug extensively twice for 1/16 south. road deep evidently washed out in past years. found 1/64 stone south above 1/16 but line was off too far west. so set C/M N & L 2634.55
– set 1/16 rod south at 1317.28
RP 1/4 corner. Dist N side tele pole E 23.0.
fence running east N. 2.0' Center N-S road W 5.0'

1/4 Cor 20-21 Kalmar 107-15 12
#752106

6-8-76 Dug on N. side of Kerr's C.I.M. Found nothing. Road cut to clean clay approx 4' deep. Covered line of fence E.



Gov't Meas Knock 55½
10.00 SCI 14 Brass Pin in mound with pits, chained stake 1 deep - Bearings Trees N E & S.W.