10-7-68 set C/M over stone - rod by side - glass ①

1/4 Corner Center 24 Kalmar 107-15 #75209
1st Poster
L Miller

5-1880 Hunter unrecorded Book - P111 No 358 & 24

set stone 4 x 6 x 24 at inters lines

1/16 north set stone M & L 20.01. 5x5x16. (1320.66)

1/16 east set stone M & L 20.04 3/4 5x8x21 (1323.14)

10-1968 J Kerr.

found stone at center with backhoe in line fence south.

found 1/16 stone north - run line from this stone to corner post at 1/4 24 - center stone found .85' east of this line

- dist center to 1/16 stone north record 1320.66.
- " " " " " actual 1320.25
- meas " " 1/4 C/M east record 2646.28 A 2646 ± (Poster)

set C/M over stone (lowered) & rod rather deep as road grade slopes to east subject to wearing down. stone here 4 x 6 x 16

- Disc east edge power pole #21792 S. 28.35
- corner lies in line fence south
- " " 3.0' south of present road.
- Corner post as S 1/4 24 may be very close or likely 1 or 2 feet too far west as line from corner just north to 1/16 stone found came .85 west of stone found.

6-9-72 Co surv. meas from final C/M at 1/4 23-24 east to prop cor rod. 1331.65 JKerr 1331.55
Meas 1/4 23-24 to center. 2633.1
- also set 1/4 24-25 (C/M) by line described above 2.55 E
of line meas - 1/16 N of center (stone) & Co post at 1/4 24-25. See 1/4 24-25

1/4 Corner Center 24 Kalmar 107-15 (2)
#752409

2-21-85, Center 24: Could get no dip at all. Road appears newly graded. Old disc in power pole still in place.