5-9-1963 CIM set by county B 264 #752705 ①
4-6-1976 = CIM set up To Sortake - Same exact Location
section corner 27-28-33-34 Kalmar 107-15°.
3-1871 Perry P154 no 197 S27 D Beatty.
found stake set prevens survey in place orig stake.
1/16 east set stake in road and "guard post" 13' north
N&L 19.84½ to S¼ 27 a stone found.

7-1893 H Fraser P525 no 490 S32-33 Byron village
found squared stake 2 rods south of fence corner past.
running north. set stone 2x4x15 on top of stone 3x6x6.
- Meas west 39.93⅔ To stone 6x6x24 set N&L.

over)

5-1900 Robt Fraser P680 no 605 S.27 Christensen found squared stake & stone 2 rods south cor post P525 and in about North Track of Road

- Meas north 40.02 to stake & 3 stones set M & L this survey.

Co Hwy Dept B264.P1 - found stone set CIM 5-1963

Disc power pole NW 54.90 ~~54.83~~

" " " S.S.W 50.69 ~~50.67~~

SE corner foundation building N 37.22.

Meas west 5270.34 | Top Cont'd C/L N=NE — 52.70

Meas east 2629.73

4-6-1976 Co. Surv. - dug out Co. H.D. CIM and went down To Top of 2"x4" Stone (Top 3'+ deep) Set 1' Long piece 1½" pipe on S.S.de and set new CIM up To B.T. Surf and re tied Corner.

Section Corner 27-28-33-34 Kalmar 107-15

#752705

R.P.'s: Disc in power pole N.W. 54.83
Disc in power pole SSW 50.67
S.E. corner foundation building N37.22
Top Center culvert NE 52.70

Note: Bound Book at MetBoffice dated 10-1919 — see copy at back of Blue Notebook.
Indicates Stone found 20" deep and Tied To Shed (SECor) N. 34.0
Meas. South To 1/4 Cor. 2635.5'
Gen'l Meters Karnak 1854
80.00 Set post for corner to Sec'd 27-28-33-34
Erected mound with trench, pits, charcoal
Stake & Orange Orange streaks at each angle