1 4-6-76 Set CIM over 1/2" pipe M&L #752706

1/4 corner 27-28 Kalmar 107-15

3-1871 Perry P154 No 177 L27 D Bently.
found orig stake standing
1/16 east set oak stake M & L 19.84 to center 27.
center 27 (a stone in mound & pits set. No 145 P106.

5-1900 Robt Fraser P680 No605 L27 Christenson
Could not find orig stake P154 ground plowed & washed.
drove stake M & L 40.02 and set 3 stones around it.

Note: This M+L Corner by R.F. probably not correct
Should have run E-W 1/4 line in Sec. 27

4-5-76 Found ½" pipe near corner post of 3-Way fence

4-6-76 Set C.I.M. as near to M&L as possible. A large boulder in the way and could not move it. Had to move pipe location .15 North and .50 East. Set C.IM. over ½" pipe. Corner falls 1½' East of corner post.

Cont Works Karnak 1551
Y0.00 501 11 5001 feet
Bur Ark C 500 W130
" " 6 521 E 100