6-29-1964 set C/M over 3/4" X 12" iron

#752804

1/4 Corner 28-33 Kalmar 107-15

7-1893 W Fraser P 525 No 490 L32-33 Town Board.

Corner gone, dug rod square, set stone 6 X 6 X 24

M & L 39.93 2/3 = 2635.82 to section corner found east, set west

---

stone found and maintained by Co Hwy Dept.

with rod riser in new grade.

6-1964 J Kerr reestablishing corners.

set C/M over 3/4" X 12" iron in place iron found.

Bound field Book at Mc+B office - dated 10-1919 See copy at back over RPS of Blue Note Book.

Indicates Something used as 1/4 Cor. — Meas. So. To Cen 33. 2622.5

+ south end concrete culvert — LE 69.9.

Disc — tele pole. — NE 112.7.

" — power pole. — LE 59.97.

" — treated corner post — LW 60.65

" — tele pole. — NW 55.02.

" — top corner post — NE 64.06.

Gov't Mon. Iron Knock 1501
40.00 Set temp. 1/2 inch post
West on true line between reds 25133
40.00 Set 1/2 inch post in mound 40.00
with knob, drill, chiseled stakes &
Copper Coin - scribed WE 1501.

Hunters RR Notes 2049 South Tie & RR tracks