6-29-1964 set C/M over 1"x14" pipe. #752805

section corner 28-29-32-33 / Kalmar 107-15

7-1893 W F Lacey P525 No 490 & 32-33 Town Board.

corner gone. dug rod square 2' deep.

run line E 1/4 32 to E 1/4 29. set point Midway 39.96 1/2.

" " N 1/4 32 to NE 33 " " 1/3 dist 39.93 2/3.

set stone 5x8x22. - which located corner favorably.

Co Hwy Dept. found & maintained corner many years.

6-1964 J Kerr set C/M after finish grading.

corner in & black top in line fence south 2" below B top.

Disc in tele pole N. 3768.

(over 1/16 W

Corner to Byron Village

1/16 corner between SE 29 and S1/4 29 107-15.

found stone set 1/2" pipe on stone. (no records).

cross culvert headwall west 21.5

Northwest corner house. SE 42.7

B 264 Co H D Pl. 1962 found large spike over painted boulder.

Hub S 68.3

Meas west - 2633.38 Meas east 5270.34

Coal Mo 13 Kan-ak 1951

50.00 set post to corner to stake 28-29-32-33

reset monument with brass pins, chained

stake & orange ribbon at each angle