5-9-1963 CIM set by Co Hwy Dept. #752904 (1)

1/4 corner 29-32. Kalmar 107-15

5-1871 Perry P162 no 185 S 29-30-31-32.
found stone monument set witness stone 50 lks west.

---

6-1886 Hunter P412 no 401 S 32. J Hicks.
found stone and witness stone line of fence running west.

---

7-1893 H Fraser P525 no 490 S 32-33 Town Board.
found stone (city plat). and witness stone 2 rods west.
drove iron pipe beside stone.

corner maintained - C/M set by County after road building & surfacing.

Pipe tel pole L.E. 36.28
" " " S.W. 37.21

7-1927 Co H D B51 P61 stone mon.
Meas south 2625.0 to ℄ highway at what time.
also stone 33' west.
B84 P1 tile iron pipe. Lp PP N.E. 65.2 - Lp PP S.E. 56.0

B 264 Co. H D found corner. set C/M 5-1963 brs above
Meas east 2633.38'

Mc Ghie meas west

Hunters R R Notes 1697' south to ℄ R R tracks 1863

Falcon 1/4 corner 29-32 #752904 | 2

Cast Metes Karrick 1957

40.00 set temp 1/4 steel post

West on true line between secs 29 & 32

40.00 set 1/4 steel post in mound V 9°21'

with trench, pits, charred stakes &

Orange Orange stubs NE & W

---

12-4-82, 1/4 Cor 29-32: Found 1" pipe in new blacktop. Checked .02 long to lot pin West. Found NW, SW, and NE lot pins of County Sled set by County Surveyor in 19____ which indicate pipe should go .09 N and .03 West. However, fd nail set 465.93 East on the Sec. line in 1974 and pipe lies on line from SE Cor 29 over this nail and 465.95 from it.

"752904" 1/4 COR 29-32 107-15 7-23-99 EPA MC

FOUND PIPE W/ PLASTIC CAP @ SURFACE. CORNER

FALLS IN ℄ CSAH #5 + 1/2' S OF ℄ CR 134.

CSD PP # 35 ESE 78.19

CSD PP # 40 SW 98.77

TOP NUT FIRE HYDRANT SE 53.32

SET 1" SA PIPE W/CAP AS REF. DOWN 0.5'

IN SE COR INT. CSAH #5 + CR 134. REF

PIPE FALLS 38' E ℄ CSAH 5 + 28 1/2' S ℄ CR 134

TO REF PIPE

TO 1/4 COR 29-32

VA 92° 38' 18" dd 05

SLOPE 45.93 HOR 45.88

9-22-99
GPA RF MC

✓

"752904" 1/4 Cor 29 32 107-15 KALMAR 81
SET PK NAIL @ SURFACE. CHECKED TIES.

"752904" 1/4 COR 29-32 KALMAR 107-15 10-99
SURVEY CREW SET PK NAIL AT SURFACE FROM
TIES TAKEN IN JULY.