5-18-1966 set CIM over remains fence corner, Carol SW 31 Kalmar

section corner. township corner - Dodge Co line
SW 31 Kalmar. 107-15, NW 6 Salem 106-15.
1863 Compton P71 no 101 S 31.
set stone at corner. 3½x7x7.

#753105

5-1871 Perry P162 no 185 S 29-30-31-32.
found stone set P71 from orig bearing trees.

6-1871 Perry P168 no 186 S 31 re-survey
found stone set P71 tested orig B trees.
Meas east 19.21½ then 20.00 to section corner

10-1884 Hunter P393 no 384 S 6, 7, 18. N Bale stat.
found engraved stone set by D County surveyor. (over)

- Meas east 39.11 to 1/4 corner then 39.94 to sec cor.
- Meas south 39.82 to 1/4 2628.1 " 39.77 " " " (2624.8)

this corner badly out of line to be on town line.

1966 Meas. twsp corner east to 1/16 ~~1262.27~~ } Revised
" above 1/16 to N 1/4 6 ~~1314.53.~~ } msmts
" twsp corner south to W 1/4 6-2627.6 } in 1974

6-1870 Perry P 126 No 159 L6.

found small stone, broken glass. set new oak stake.
- 1/16 east 19.15 1/2 then 19.80 1/2 then 40.00.
- 1/16 south 19.89. M & L.

5-1966 J Kerr found lower portion of big stone.
set C I M. over stone remains

fence line running south on west side of road	W	33.0
Dice power pole. & tele pole comb.	E	40.8
" guy pole.	W	40.4
corner lies slightly south of fence line running ~~East~~	S	1.0

Section corner, township corner

#753105 (2)

S. W. 31 Kalamazoo 107-15, N. W. 6 Salem 106-15

Gov't Notes, Kalamazoo, 1854

79.22 Township corner, hard ground - 11 ins