5-24-1966 set C/M over 1/2" x 24" rod by line & meas.
6-12-74 set C.I.M. over rod and stone
section corner south 31-32 Kalmar Do 7-15-
north 5-6 Salem 106-15.

5-1871 Perry P162 No 185 d 29-30-31-32. (1)
Corner gone - set point later removed #753205

6-1871 Perry P168 No 186 d 31.
removed corner P162 - found old stake set stone
3 x 10 x 21 took B Tree (now gone.
-1/16 west set stone 3½ x 8 x 18 M & L 20.00 with witness
stone 4 x 7 x 14 75 links north.
-1/16 north set stone 2 x 9 x 14 M & L 20.05 ½ stones
on north and south sides.
-1/16 Center d E¼ 31 set stake on E-W 1/16 line no meas

May 1863 P.C. Compton Pg. 71 No. 101 shows Sec Cor. (See Survey) over)

10-1884 Hunter P393 no 384 L 6-7-18 Nelson Bale etal.
found stone and B tree - 39.94 west To L ¼ 31.

6-1886 Hunter P412 no 401 L 32 J Hicks.
found boulder. set by Perry P168.

7-1893 H Fraser P525 no 490 L 32-33 Town Board
found stone P412.

5-1966. J Kerr found iron rod by small flat stone by McGhie
over deep fill, no chance of corner being correct as it.
dug 4' deep. still in road wash & erosion debris.
set C I M over 1½" x 24" rod. on line projected from township
corner over L ¼ 31 at prop distances which lines with fence S.
Dice west side power pole in fence line L L E 29.5 } 2.18 L to
" north " " " " west lot line W L W 149.1. } McGhie rod still in.
corner lies in line Fence a little N L road - 2635.65 W to ¼ cor.

#753205 (2)

Card # 2 on S 31-32 Kalmar N 5-6 Salem
C I M's at 1/4 5-6 and S E cor 6 Salem may not line north to
N cor 5-6. Perry set stake at 1/4 5-6 on section line 20 chs
north of S E cor 6 P 126-6-1870 before he made either survey
of S 31 when he set & reset S E cor 31 Kalmar. Could check line
if present corners south but likely could not rely on line W Traces
found stone at 1/4 5-6 Salem found when C I M placed.

7-17-70 Co surv 96° Lot remeas line west to check 5-1966 got:
found S 1/4 31 at 2634.73 -1966 2635.65 R 2639.34
" S 1/4 to 1/16 W set 1966 at 1314.12 -1966 1314.53 R 1320.0
" 1/16 W to Twp cor found 1966 1262.95 1966 1263.27 R 1268.2
7-16-70 Meas north to ¢ Par. 2659.3 R 2647.2
found 1/16 fence west at 1338 ±
-run aerial from 4.5' south of 1/16 fence at West line of S 1/2 S31 over point (over
50' south of corner post at 1/16 center SW 1/4 31 - (chad not find tracks by Perry.

found this line to meas E-W fence about 500' west of section line 52' south only 2' off. Came, line came about 5' south of corner W-S fence.
set up line between S^cor 31 and S^cor 32 like Perry reset line with big kink at
¼ 31-32 also claimed by Compton & Perry finally found Comptons corners.
-this made 1/16 between SE/39 and E¼ 31 under fence or slightly east.
and some 6' ± d/f fence meas

7-20-70 dug extensively at 1/16 north found limestone same meas as
perry set but lying flat. found stake quite deep 2' W, 5'S f
fence corner. accepted as corner until proven otherwise set 4'
rod with stone found on N side. 1333.2 south to C/M.
and 1324.1 north to ℄ pave. which was set 1.87 south of ℄
a lead plug in hole. Making meas N 1322.23 R1323.63

6-1925 J Kerr B-6 P20 Sinclair survey
found post shattered limestone replaced with boulder 1.3'x1'x
running to a point. set over stake driven below stone
Meas 1 mile N 5265.2

#753205 (3)

Section Corner South 31-32 Kalmar 107-15
North 5-6 Salem 106-15

6-18-1974 Co. Surv.

Dug with backhoe and found the stone & stake remains under it. set a 3/4" x 3' rod in stake hole & layed the boulder on the E. side - Set a C.I.M. over All.

Corner falls 11.62' North and 2.4' East of J. Kerr's mony.

R.P.s

Punched cross E. end 18" C.M.P. S.W. 86.6
Nail top center single post S. 41.51

M.H.D. disc W. side P.P. S.E. 50.87
top center tele box N.W. 32.85
corner falls in line with fence
north and on the north edge
of the traveled road.

Govt. Mon. Karnak. 1951

30.00 5x1 post and drive 10" chained stake corner to sections 5-6-51-52. Built mound with trench. Planted 5 E. Osage Orange seeds. + N.E. Apple seeds.

follow township corner. #753205 G

1/16 corner. between 1/4 31-32 and S 31-32 Kalmar.

7-20-70 dug large area after meas. N-S line from ℄ of pavement south 2657.3 also run random line on 15' offset west for line between S 31 and 32. Very confusing as record of S 1/2 was 2647.2. - found recorded size stone lying flat and defined stake at 1333.2 N from CM set as S 31-32. - drove 4' rod in stake hole with stone on N side. - corner 2' west ℄ fence south and 5' south ℄ fence west. - corner came 1.15 east ℄ direct line betw CM at SE 31 and hole in hwy mon at 1/4 31-32 area.

8-18-70 set lead slug in pavement 1.87 S of ℄ par and on projected line from old pipe at NE 31 over 1 1/4" pipe at 1/16. South set by line and meas from west. so actual line ℄ above 1/16 not sure Meas S 1333.2 // N 1322.2 over. same 1/16

true M & L. of this 1/16 rod would be. 1327.7 or 753205 h
5.5' south and 2.44 east of present rod.

1/16 corner between 29-30-31-32 and 1/4 31-32 Kalmar (2)
record- Perry 6-1871. set stone 2x14x28 M&L. 1311.75
with witness stone 33' north 2x14x17. - Stone 1/4 31-32 3x17x21.
Stone NE 31. 4x14x23. #753205 I
CIM set by Co H D and used in subdivision & school surveys.
original stone and point assumed in early surveys all lost.
- ignored east line entirely in setting present corner. ac
Perrys 1/16 stones west all found. at 1316.73 from. 2
corners found. or 1/16 center NE 1/4 31 and 1/16 betw Centers 31 & N 1/4 31.
- placed 1 1/4 x 30" pipe on exact projection and double meas.
which fell. 1.2 south and 3.65 east of county CIM (removed)
- final meas N to tall pipe ac NE 31. 1310.6. 1311.75
- " " pipe to center railroad on exact sec line.
309.15 or 1619.75.
- final meas to ℄ pavement 1308.73 or 2619.33
(over)

-final meas to lead slug set exactly on projected line from tall pipe at NE 31 over 1/16 pipe set 1310.6 or exact double or 2621.2 R. 2623.5 1.87' S & par. removed C/M and set 120 D in its place in case point needed for some purpose.
- set 3/4" x 16" pipe as RP 75' north in school lawn. pipe came 2' south and 7.23 ENE of center small pine

753205 J