4-21-1965 set C/M. one 1/2" x 12" pipe #753209 (1)

1/4 corner. Center 32 Kalmar 107-15.

5-1971 R Perry P164 no 185 Secs 29-30-31-32.

Post #13 " found a stone exactly on line between 12 (W 1/4 32) and 47 (E 1/4 32) but 4 1/2 lks (2.8') east of direct line between 5 (S 1/4 32) and 26 (N 1/4 32) did not disturb stone or place any other corner. In Survey No 186 he corrected W 1/4 Cor 32 24 1/2 lks North So Center 12 1/4 lks So of E-W 1/4 line

6-1886 Hunter P412 no 401. S 32 J W Hicks.

Although a corner stone is recorded in survey no 185 as post #"13" no stone or other evidence could be found. So me projected line from N 1/4 32. (stone found) South to

S 1/4 32 stone found. and measured. from this line along south side of Huche. North fence. running east. through to E 1/4 32. (prone fence corner post). without fixing the exact north line of the 1/4 section which could easily be done by projecting the E-W 1/4 line across the section, and as the main object of the survey was to define the N & S. line between Huche and Dresbon(?) from 1 to 2 (N-S 1/16 line of SE 1/4 32, with this done. it was not deemed advisable to trace the entire north line of 1/4 section.
1/16 E or "2" came 19.90 (1313.4 M & L!

S line SE 1/4 set "1" or "found stone exactly M & L. 19.92 (1314.72

April, 1861 Samuel McDowell Pg. 66 No. 93 Did breakdown in S.E. 1/4 Sec 32 of 3 N-S Property splits

#753209 (2)

Card # 2. Center 32 Kalmar.

7-25-1893 W Fraser. P525 No 490 L 32 & 33.
for Town of Byron.

found bottom of post on direct line between D & F or N ¼ and L ¼ sec 32. did not test it the other way as only wanted line of road.

C/M set as corner from maintained corner of unknown origin partly county state and local surveyors. will have complete data on C/M

47.2. NE to center hydrant.
13.1 L to center pavement
40.0 WNW to dice in PP.
43.6 N.E. to dice in tele pole.

1966 Co H Dept B320.

1/16 between Center 32 and N 1/4 32.

Meas W 2637.84 with 1/16 rod at 1319.62. likely north.

a 3/4" rod in B top.

48.52 S E to center hydrant.

40.75 SW to Sp in PP.

36.46 S E to Sp in PP.

1973 & April 1974 Co. Surv.

found Center Sec. - C.I.M. To be 3.5' Too far South and 0.9' West of The True 1/4 lines.

Did not change The Corner or The Mond.

7-14-77 Dug down to check conditions as MHO had removed CIM. Found orig subdiv. Found nothing.

1/16 corner on N-S 1/4 line of N 1/2 section 31. (6)
1/2 mile west of SW corner school lands #753209
8-14-70 dug for stone 5 1/2 x 5 1/2 x 12. set by Perry M&L
betw Center 31 and N 1/4 31. No meas given.
- meas from piece of steel post set at 1/4 30-31 south to
stone found. 1311.06 - this stone on line with 1/16 stones
west (checked 9-4-73) and very near on line from whole mile
on E-W 1/16 line if anything a link projected from west would fall
a few tenths south at each end.
- set 1/2" x 2' rod with stone on S side down 8" 4' S of rod
76.6 SW ly to center stump 16" high pine
148.75 SW ly to SW cone block warehouse type bldg.
143.15 SSW ly to SE " " " " "
31.75 SSE 11' E of S to bottom screw on E side tele cable control post
192.0 SSW to nail on W side utility pole up 5' (machinery in betw)

meas E M&L 1316.73
meas W when?

1/16 corner Center NW 1/4 31 Kalmar. 3/4 mi west of SW cor sec 6
stone 5½ x 6 x 14 6-1970 P 171 # 7 corner. set inters lines.

8-17-70 dug with tractor easily found 2'- down. 5½ x 6 x 13
leaning slightly easterly with 6" cube type stone on W side of
base of stone - set 1¼ x 2' thin wall pipe in center base of stone
with ½" x 11" pipe risers in lower pipe. stones on E-W-N sides.
- corner final on exact line E & W. did not dig for 1/16 W line.
no mark on this line yet
32.2 due N to dike in corner post
9-4-73 road to be extensively graded all trees & fences
removed no poles or buildings anywhere near.
set 12" long tee T rod (Kassler) at 60' north a little west
of N-S fence and ¾" pipe on transit line at 100.0' only RR

T5360 F

Mica corners in Byron Village worth referencing. follow Cente 32.
Reg stone with cross in SE corner intersection the center of which is 3/4" iron described & referenced. as 1/16 corner N of Center 32.
this stone is not block corner but ± 753209

20.24 SW to center top of hydrant.
10.18 W To conc nail in bottle cap N side power pole.
SE (Skant) to SW corner house.