5-1977 Co. Surv. fd 5/8" pipe over C.I.M. in S w ly S. side of Rd inter.

5-24-1963 set C/M over stone found. (1)

#753304

Elmer Christgau helped find in 1965?

1/4 corner south 33 Kalmar 107-15

North 4 Salem 106-15.

7-1873 Hunter 233 no 235 S4 Fairbanks Strain

corner gone, set temp point M & L. 40 chs. Jacobson.

10-1921 Ch Larson. P 362B. 4 watts Bros.

corner gone set stone 3x9x24 M&L. 40 chs.

1/16 south set Concrete slab 6x10x24 at 19.56 then

20.00 to center 4 a limestone 4x14x15.

also set limestone south 7x8x14. 29.56 from N 1/4 4.

1963 - BK 88 - P 8-10

4-1965 Ster S 33. B86 P 51

found stone after much digging & measuring.
set C/M over stone found.

Dec power pole E & E 35.9.
" " " guy. W & W 29.5.

Corner lies 1'± south of south edge traveled road
running west and near on west edge road south.
- meas East & west 2639.9.
- " south 2609.0 To center.
recorded 2611.0

9-3-71. proj line from S 432 over 1/16 E and S 32-33 to area of S 1/4 33 and found proj line fell 13.15' N of S 1/4 33.

Bound field Book at MC+G office. Date 10-1919 - see back of Blue Notebook for copy
indicates Stone found 16" deep Meas. East 2634.6 & N. 2622.5 To cen. 33 ?

1/4 CORNER SOUTH 33 KALMAR 107-15 (2)
NORTH 4 SALEM 106-15
6/12/90 FD PIPE/CAP # 14888 IN SW COR.
OF INTERSECTION OF TWP RDS #753304
CSD IN P.P. # 40 E.S.E. 38.90
OLD DISK IN GUIDE POST S.W. 29.32
℄ RD SOUTH EAST 8'
℄ E-W RD NORTH 11'

1/4 corner South 33 Kalama 107-15

North 4 Salem 106-15

(3)

#753304

Gov't Notes, Kanuck, 1854

40.00 Set post, + drive 5" chained stake to quarter section corner. Built mound with trench. Planted S.E. Orange Seeds, + N.E. Apple seeds.