#753305 (1)

11-19-1963 set C I M only limestone found.
9-71 pulled C I M set ½" rod - 7-6-72. Reset Corner with C I M

section corner south 32-33 Kalmar 107-15
north 4-5 Salem 106-15

7-1873 Hunter P233 no 235 S4 N Fairbanks, Strain Jacobson.
found old stake center road in line fence south,
owned by Mr Dearborn to be on line old stake.
set stone 3x7x16"

6-1886 Hunter P412 no 401 S 32. J.W. Wicks
found stone center road in line fence south. P233.
-1/16 west. found stone N 9 L 19.92. To stone center cross roads

April, 1861 Samuel McDowell Rg. EC No. 93 used 32C. Corner
for Property survey in S.E 1/4 Sec. 32 & N.E 1/4 Sec 5 106-15 over)

10-1928 Chas Larson. B 362 B 4 watts Brac.
found sec cor limestone 4 x 7 x 16 P 233.
- south 29.57 to limestone 3 x 14 x 17.
then 10.00 to W 1/4 3 recognized as 1/4 post for 30 yrs.

11-1963 J Kerr
found limestone set C I M over stone.
RPs transit ties 1/2" pipes north & south 33.0'
9-3-1971. removed C I M for grading set 1/2" x 18" rod
- pulled 1/2" pipes - set at 50' and 100' south on transit line
- found that S 32-33 lies 6.57' north of direct line between
S 1/4 32 and S 1/4 33 for road layout 7-6-72. rod near gone.
next corner over stone. by transit and 2 above reference pts

South 32-33 Kalmar 107-15 #753305 (2)
North 4-5 Salem 106-15

Govt Notes, Karnak, 1854

$0.00 Set post and drive 15" chained stake to sections 4, 5, 32, 33. Built mound with trench. Planted S.E Osage Orange sticks, 4 N.E Apple sticks.

6/12/90 FD CIM WITH BROKEN TOP, MON IN GOOD SHAPE OTHERWISE TP'S
CSD IN WEST SIDE LARGE POST SO 43.58
& E-W RD SOUTH 4.0'
NAILED SURVEY SIGN ON POST SOUTH