#753405 (1)

4-22-1965 set C/M over 5/8 x 12" rod
7-6-72 reset corner with C/M removed 6-1970
section corner. south 33-34 Kalmar 107-15.
Check Corner
Could be Too far East RB = North 3-4 Salem 106-15.
7-1873 Hunter P 233 no 235 S 4 Fairbanks, Strain
found stone with stake on east side, Cutler road. Jacobsen.
- Meas west 40 chs to temp stake set M & L.

10-1921 Chas Larson P 362 BB 4 Wattle Bros.
found limestone 4x8x24. P233.
1/16 - with set concrete slab 7x12x20 19.43
then 20.00 to 1/4 3-4. a hard head boulder.

Bound Field Book at M+B office - dated 10-1919 - see back of Blue Note book indicates stone found 18" deep + Ties given. Meas. West 2634.6 - Meas. North 2635.5

4-1965 corner gone. replaced with C/M over 5/8" x 12" rod.

from 1931 Minn Hwy Dept notes. Probably Not used.
1924 & M & L from west.

Disc power pole to L. 29.5-

3" Minn RW monument N 63.0 S-

Disc tele pole. ~~NE 84.6~~ gone 6-9-70

this corner really set by doubling from SW 33 ones
S 1/4 33 2639.9 within .1' of record.

6-9-70 Co surv removed C/M. Checked rod below set 1/2" rod in place - 2.95 south from south edge conc pavement.
4.0' east of line of fence north
- NE edge of T steel post for "for sale" sign easterly post SE 57.81
see Card 2 for 1/16 east.

#753405

(2)

Card # 2. S 33-34 Kalmar 107-15'
N 3-4 Salem 106-15

6-8-70 found 1/2" rod set M & L east on 1/16 corner.
lowered rod to some 6"+ deep. to same corner
- corner lies 4/3' south of south edge pavement
- punched cross cut on west end drive culv. 2nd ridge as first ridge hidden by culv clamp SW 43.39
- punched cross cut on east end drive culv on first ridge 4' west of S. 23.64
- NE corner of attached garage SSW 112.5'

7-6-72. found rod set 6-70 after removing CIM for grading road shoulders. reset corner with CIM

8-5-77 Dug on West side of CIM to check conditions for digging further West with backhoe for stone recorded in old field book dated 1919 in McGhie office. Found area cut to clay 14" down.

Govt Mon, Found, 1951

80.00 S of post I drove 10" chained stake to Sections 3, 4, 33, 34. Built mound + mark. Found SE Corner Orange stake + NE Apple stake

6/3/92 County Surveyor fd CIM in good cond.

12.9' north to ℄ of CR 34

34.62 south to bottle cap in PP

Set ½" ref rod RP 5' west to wood fence

Cont →

SECTION CORNER S 33, 34 Kalmar 107-15 (3)
n 3, 4 Salem 106-15
#753405

6/3/92 Cont.

~~No~~ ref rod

~~Brg~~ CIM TO TOP OF RADIO TOWER
35° 42' 19.5"

To S 33, 34 (CIM)
VA 94 49 21 dv10
SD 38.95 HD 38.805

6-24-93 Set 1" sq pipe w/cap a surface of CR #34 over CIM Tie out in 1992 R.P.'s & CR#34 North 12.9'

The corner falls ± 9' East of Wood fence running South
Checked 1992 Tie to bottle cap in P.P. South 34.62'