#753505

4-21-1965 set C/N. from Minn Hwy Dept notes
7-6-72 re-set C/N. Over iron found below (1)

section corner south 34-35 Kalmar 107-15-
north 2-3 Salem 106-15.

5-1879 Hunter P360 No 351 S2 D. Fallon. etal.
found stone center of road in line old fence,
agreed by adjacent land owners as replacement of stake.
- 1/16 each set stone 2½ x 8 x 24 M & L 19,89 - 1312.74
- Meas south 39.35 to stone 5 x 8 x 15 replacing stake.

4-1965 J Kerr reset corner from Minn Hwy Dept.
notes on station and on line between RW monuments
as quoted on Hwy notes.

over)

Rec	tele pole	~~NW~~	~~49.3~~ gone 6-8-70
"	power pole	SW	67.23
Munn RW monument		~~N~~	~~34.0~~ " "
Center line pavement		S.	15.8

6-8-1970 removed C/M checked rod below set 1/2" in place.
– Lard nail W side PP 40117. just under 4 6 5 number N 24.6
– punch mark in center road on W end field drive curb ENE 83.3
– Iron on S side road 3rule in place. Sta 216+69.5

7-6-72. found iron reset corner with C/M. took additional RP. hard nail in knot on N side guard post 3' N of W 17.94

Section corner South 34-35 Kalmar 107-15
North 2-3 Salem 106-15
(E)
#753505

Gov't Notes, Kamrick 1954

80.00 Set post and drive 15" chained stakes to corner sections 2-3-34-35. Built mound with trench Planted SE Osage Orange seeds NE apple seeds.

6/3/92 County Surveyor Fd cim in good cond.
Rps 16.0' South to E of CR# 34
24.63' north to bottle cap in PP #40117
(SET ½" REF ROD) Rps ±5' NW to middle guy wire, ±5 NE to east guy wire,
23.34' north to bottle cap in pp #40117
To S 34,35
@ REF ROD VA 88 21 06 dv 06 SD 47.905 HD 47.885
∠ RT S 34,35 to top of radio tower 159° 14' 53"

7-12-93, Set 10" C.I.M. @ surface of CR # 34 over bottom half of old CIM in shoulder of County Road 16' North of ℄.

6-28-93 - Turned Out June 1992 Ref ∠ of 159° 14' 53" for 47.885'. Set PK Nail.