X

#753605 (1)

section corner south 35-36 Kalmar 107-15.
north 1-2 Salem 116-15
5-1877 Hunter P 360 no 351 S2. O Fallon etal.
found stone in center road in line fence south. claimed
set at site of orig corner.
— 1/16 west set stone 4 x 4 x 20 M & L 19.89.
— south set marked stake 29.47 then 10.00 to 1/4 1-2.
a fence post in mound.
— also set marked stake west of above stake 19.99 which
was set on N-S 1/16 line 10 chs from E-W 1/4 line 2.

Now cross cut in exist & pavement from
Minn State Highway notes on road construction 1930 S.
No R P S (over)

6-9-1970 Co surv. found long cross in ℄ pav. also other marks suspicious as to being also crosses. Cross accepted as corner. Ties 33' east of RW marker on SW corner intersection and 33' west like marker at SE corner intersection. (SW marker badly tilted)

- hole in top 3" mon. 286+84.5 SE 59.94
- " " " " " NE 58.65
- these mon. are not opposite at 90° from ℄. only south mon used as 33' to set cross in pavement. the northeast mon moved be. about 30' east on 90° from ℄.
- pepsi cap on NW side new powerpole (no number) SW 60.5

Cross used most easterly and longest & deepest one.

Gov't Mons. Rock 1854

30.00 St post & three chained strokes to southeast

1-2-55-3C Bill owned with trunk plated S.E.

Osage Orange 8-6, - N.E. Apple 5-6

SECTION CORNER S 35,36 KALMAR 107-15 (2)
N 1,2 SALEM 106-15
6/3/92 County Surveyor fd chisel cross in conc. checked ties 59.77' SE to MNDOT mon #753605
58.58' NE to MNDOT MON
(SET 1/2" REF ROD) RP's 22.52' NE to PP# 50022
11.0' west to E of N-S Rd.
@ REF ROD
RT S 35,36 to top of radio tower 307° 39' 03.5"
To S 35,36
VA 900004 dv12
SD 114.135 HD 114.135
Jackhammered conc. out so mon can be set after blacktoping.

7-12-93, Set 1" Sq pipe w/cap in ℄ CR # 34 at Surface of new blacktop at PK location. Set out 6-28-93 checked Mn/Dot Mon. Ties OK. the corner lies with ℄ south ± 5' East of ℄ North.



6-28-93, Turned out June 1992 Ref ℄ of 307° 39' 03.5" for 114.135 (Set PK Nail)