8-16-72 found township corner monument 10" deep
7-6-73 set 6" CIM over Stone
section corner township corner. 4-18-75 cert

Northwest corner sec. 6 Quincy 107-11 #81305
Northeast corner sec. 1 Verda 107-12
No know records except law required setting corner 1878
- found 5/8" Telephone crossbar 10" long set as assumed
corner by unknown surveyor
8-16-72 used 11 Barton Cat to plane road surface
found 8"x8" top limestone monument set by Hunter
under stab law. - drove 1¼" pipe 2' long on E side
Corner Came 5.2' east and .3' north of bolt found & removed

over RPs

stone only down 10" or less ~~Can work set C/M.~~
- set short drag tooth which must be rechecked when used.

bolt
48.8 SW to PK in SE side PP # 32882 44.98
bolt
4895 NW to PK in NE side PP # 32883 45.05

drove 1¼" x 2' pipe on each side of Mon down 8"+

Center road south graded 8-1972 start abut 5 West & Twp corner running thru center bridge south to P.O.T on hilltop abut 400'± north of W'46. P.O.T on direct line W'46 to Twp cor. no slight trunk at that point Center bridge rails - W'46 line .62 east of direct line bridge rails are 21.5 apart and section line comes 8.0 from east rail