6-25-77 CIM

#813605

section corner north 1—2 Quincy 107-11. & Winona County.
Set field B-9 p 61-67
10-11-1900 H Fraser P692-8 no 615 & 2-3 10-11. (over)
found stone at corner and stubs SE & SW B trees
which checked correct - new B tree 8" black oak S 16½° W 33 lks.
drove stake by side of stone
Meas west to 1/4 cor stone 39.78 (2625.48) which proved 9.9' (1/5 links) too
far east for midway and 6 links too far south for line. accepted 1/4 cor
and section corners as true corners (396) but not stones west of 1/4 corner.

Gov't Notes: Sept. 1853
Set Post for Corner (line Tree - 12" Black oak 5.71 chains South.
B.T.'s Burr oak 14" N 74° E 97 links // Burr Oak 8" S 80° E 127 links
Black oak 12" N 4° W 315 " Black oak 14" S 80° W 112 "

Parties involved in Survey no 615 - L. Risley - O H Kingsley - J D Bateman - Wm Salesbury, Peter Fender, John Fender. C L Holdridge - Geo E Purvis - H C Richardson - 23 days

6-28-77 Found 4"x7"x14" limestone with 3/4"x18" bolt on E side of it - Top stone down 2½' in Sh slope Set bolt back on E side and placed lots of junk around the stone with 20" CIM above it, Corner ±7' East of drill steel shaft which we removed.

R.P.'s: Spike in Telephone pole NNW 27.55'

60 p Spike in S. side of 48" Willow Tree West 11.1

℄ of driveway on curve East 15'

Corner lies 2' East of ℄ Main Road to North.