5-22-1965 set C/M one orig stone found.

#823005

section corner east 25-36 Farm 108-13

11-1886 Hunter P 416 No 405 L 36. E Raymond. ①

Corner gone - meas NE 25 to L E 36. W Searle.

divided midway 80.02. - meas south to 1/4 cor 40.01

- meas N 1/4 31 108-12 west to N W 35 197.02 short 22 links, - meas east 37.26 - west 39.98.

- set stone and drove iron rod by its side as corner.

7-1898 H Fraser P 639 No 575 L 36 F Kefer, R Moody. found all corners set above in S W 1/4 36. did not use any corners on east side L 36.

(over)

5-1965 J Kerr found 4x8x24 stone & iron bar.
set CIM over stone & iron

#19822

Disc power pole. NE 50.2'
" tele " SE 49.55'
cross in south end conc abutment W 142.1.
punched cross in north end galv culv. NE 28.2.

Disc in power pole # 146. 19821 NW 59.4

B149 P48 1946 Co H.D. found 4x8x20 L S mdge.
set 1/2" rod & tornchor above.

Co HD B 328 P3 found C.I.M. Sta 105+35.93
or 2647.3 west to PI at 1/4 25-36

Card # 2 East 25-36 Farmington 108-13 (2)
9-12-72 visited corner to run line and meas west.
found C/M tipped north badly well over 15" on top.
with at least 12" hard rocky fill over area by new grade.
#823005
- dug out C/M and entire area down to orig stone
checked by 3 remaining R P S. tele pole S E & Cal. Cable headwall
west both gone. reset C/M carefully and took 2 more R P.
all present R P S.

50.2 N E to disc on N W side P P # 19822.
59.4 N W to disc on S W side P P # 19821
28.2 N E to punch hole in top center N end 15" culv.
27.72 S E to punch hole " " " S " "

over

Run direct aerial to C/M at 25-26-35-36. a Corner now in very much doubt.
- set nail on line and on line fence running south ac ¼ 25-36
Meas 2646.34 R. 2638.68 also Cont meas to NW 36.
Meas. 2618.81 " Mile 5265.15 R 5277.36
or shortage 4. 10.7'
Comparable Meas on E side NE ¼ ach 2638.9 R 2640.66

Set by John Bull (9-1853)
80.00 Set post and drove charred stake corner to sections 25, 30, 31 and 36. Built mound with trench per instructions. Planted S.E. Osage Orange. N.E. Appleseed.