6-23-1966. set C/M over stone & 1½"x10" conduit.
#823106 (1)

¼ corner east ¼ 36 Farm 108-13
west ¼ 31 — Hab co.

11-1886 Hunter P416 No 405 L 36. N Lude,
E Raymond.
Corner missing, no evidence could be found.
set stone 4x6x18 with iron rod by side N&L 40.01.

6-1966. J Kerr.
found stone as recorded in sage with wood stake, no iron.
set C/M over stone and 1½"x10" conduit with ½"x 36"
iron rod. on east side of stone - C/M down 10"
- Corner as found witnessed by Herb Nessler, oil trucker
from Plainview before stone removed and lowered below C/M.
Cover

- Meas north no plumbing, trig addelene, 2638.9 R2640.6
Dice in power pole. West 44.0.
center cone shaped concrete corner post W. 30.2.
½"x 36" rod up 1" under fence E 50.0

Corner lines fences east and west exactly.
Corner lies 4.2' from west edge traveled road
6.3' west of center " "

Used this corner to reset SE 36, Twp corner could not set at equal distance south as north but set on line
- Meas North 2638.9 - south 2635.6.

10-2-72 set on C/M E¼ 36 - ran line and elec meas. to see corners - found E¼ to be .14 E of direct line and. 2639.84 N
2637.07 S
or 2.77 difference.

1/4 Corner East 1/4 36 Farmington 108-13
West 1/4 31 Wab Co. (2)
Surveyed by John Bull (9/10-1853) #823106
40.00 Set post and drove charred stake for quarter sec. Cor.
Built mound with trench per instructions, planted
S.E. Osage Orange N.E. appleseed.