1/4 Corner 1-2 Farmington 108-13
William B Yerby 5-54 #830106
40.00 Mound of earth & sod deposited charcoal made trench & pitts planted Osage Orange seed S & W
77.07 Intersect 2nd Correction line 6.62 lk (662) E of gr. post.

B-3-93, (PK Nail by V.E.) set 1" Sq pipe w/cap in Driveway East of corner in line of fence East as Reference. Ref pipe is ± 31½' East of ℄ CR # 11
T @ Ref pipe w/cap
X Rt Top Center of East silo of four SSW of corner to 1/4 Cor 1-2 84° 23' 39"
VA 88° 54' 00"
Slope 31.64 Hor 31.63

7-8-94 CHECKED P.K. NAIL SET BY C.H.D. AT 1993 REFERENCE LOCATION OF V. FANGMAN P.K. NAIL. THE CORNER FALLS ½' WEST OF ℄ CR 11 + IN LINE OF FENCE EAST

1" SQ PIPE W/CAP EAST 31.63