9-12-1966 Set CIM over ½"x2' rod driven down thru old orig stake remains. (1) #830504

6-27-79 Set CIM new Kane CIM.

¼ corner 5 - 8 Farm. 10 8-13.

William Yerby 5-54

No survey records of this corner.

Used cemetery land boundaries 80 rods west as N-S and fences N & S at corner to dog by.

- found real old, very pasture wood stake witnessed by Mr Ed Seim. after carefull digging. at line 241' from SW cor cemetery corner proved itself by line & US 63 & school fence west at SW 5.

(over)

set C/M over 1/2" x 2' rod driven down thru old stake remains.

- Corner lies within 2' of south edge traveled road
- corner lies one foot ± west of fence N & S.
- large nail in top new creos cor post of fence running west

24.72
S. ~~24.75~~

- bottle cap in power pole 4' W of S

+19.25 80 79

- 1/2" x 2' rod under fence

N 50.0

40.02 1/2 Set a chared qr Sec post in mound of Earth & Sod & made trench & pit planted Osage Orange seed East & West.

¼ Corner 5-8 Farmington 108-13 (2)

#830504

6-27-1979 Found the head of ~~the~~ Kyle CIM broken and deep. Broke off two more sections of the CIM and set a new CIM over the remainder and up to the road surface. Corner 8' So & and 1' West fence N & S RP's:

New: CSD East side power pole 4' East of Nail 42.17
MHD Disc in NW side 3" plum (up 5') SW 32.86

Old Checked: Large nail in top of corner fence post S. 24.72

½" pipe under fence N 50.01

Sign post T — South — 23'