#830507 (1)

section corner North 5-6 Farm. 108-13.

no records.

7-1964 J Kerr survey farm site in wab. Co.
run line from twsp cor NW6 108-13 to establish
E-W line, found wood stake in fair condition just
north of corner post of fence south between Secs. 5-6.
drove "½" rod thru stake location. No trees in area.
corner likely some 4 to 5 hundred feet east of US 63.

M.H.D { 4 meas 2639.0 from point @ S¼ 31 to field stone @ SW31
403.9' N. Sec. Cor. 5-6 To S.¼ 31 at fenced Int. E-W Fe and also HB3

S¼ 31 109-13 Dug from pipe So. 7', W. 2', E. 2', and N. 1' by 2' deep to clay. Clay worn out. Found nothing. Reset pipe (Taylor).

July, 1977

(over

5-1879 Hunter p 359 No 350 Ch 1 10 8-14.
NE cor 6 recorded as standing in 5-1868 when
Horton surveyed road from now 63 west to river.
then NE cor 6 to 4 road. 6.05 chs then 33.64 to N¼
6 stake set & found 1879.
Then from N¼ 6 to Twp cor 36.31.
-In 5-1868 NE cor in- In 5 1879 corner gone or didnt find

William Derby 5-1854

77.95 Intersect 2d Standard Parallel 605 lks E of gr. Sec Post set closing Cor. to Sect. 5 & 6 in mound of Earth & Sod deposited charcoal made trench & pits planted Osage orange Seed SE & SW.

S¼ 31 109-13

7-77 Dug from pipe (Taylor's) So 7', West 2', East 2', N 1' by 2' deep to clay. Clay worn out. Found nothing. Rest pipe

SECTION CORNER NORTH 5-6 FARMINGTON 108-13 (2)

#830507

4-26-95 5¼ 31 109-13 – FD P.K. @ SURFACE OF CR #11
DUG DOWN & FOUND ½" PIPE RESET IN 1977 7" DEEP
.03' EAST & .14' NORTH OF P.K. NAIL. THE CORNER IS
2½' EAST OF ℄ CR #11 CSO IN PP #35498 WNW 42.06'