1 ~~T 76 Set Elm~~ 8/18/62 SET 1" SQ PIPE / CAP AFTER RD GRADING (1)

section corner. west 7-18 Farm. 10 8-13

east 12-13 drono. 10 6-14

#830705

6-1879. Hunter P361 No 352 L18. H Buckholly. C Bluhm

no evidence or knowledge of corner. fences N & S on range line not known to be correct.

- Meas east to N E cor 18 76.75 10 lks short.
- unrecorded survey No 340 1/2. 6-1878 Meas 76.79 accepted 4 way fence line as correct by owners.
- Meas east 36.80 To stone set on line and pop Meas.
- fences N & S acknowledged as set by guess.

Set by John Bull 10-1853

80.00 Set post & drove charred stake Cor. to Sect. 7, 12, 13 & 18 built mound with trench per Instructions. Planted SE Osage Orange NE Apple Seed.

5-28-76 Dug 5½' x 8' x 6' deep with backhoe M&L between corner post at W¼ Cor 7 and calculated W¼ Cor 18. Corner in former marsh area. 2' of green muck under last road and on the clay. Found nothing.

6-7-76 Set a CIM over RR spike at the computed location of ½ the total distance and on line between the W¼ Cor 18 and the W¼ Cor 7 by elec. traverse. Corner falls 8' South & of C.R. #12 and in line with fence North and 7' W of fence S.

RP's: CSD in pp # 35000 SE 108.15

Point on angle iron corner post N 44.3

#830705 (2)

West Section Corner 7-18, Farmington, 108-13
East Section Corner 12-13, Oronoco 108-14

7-16-84, W. Sec. Cor 7-18: Took references before road graded. Drove 5/8" re-rod under fence running South (fe. line 8' East of cor). Occupied rod and turned 4 Rt 8°53'14" from house chimney (main straight part of stake just beneath fancy massive cap) on West side of large new home NNW of corner. to W 7-18 Measured 107.31 to corner.
(See Farmington Twp Book)
Chained 8.14 from CIM North to large spike in ℄, possible P.I.

6-5-1985, W.7-18: Set 5/8" re-rod in newly graded road (crushed rock) from transit tie taken 7-16-84.
Corner 8' So & C.R. 12. Fence South now gone and transit tie rod in danger.
RP. & CSD in W. side of pp # 44622
(REF) SSE 48.99

7/31/92 FD 5/8" REB IN GOOD COND. FENCE SOUTH NOW GONE. WILLOW TREE NOW ON LINE TO HOUSE CHIMNEY, MAYBE WHEN LEAVES FALL OFF WILL BE OK.

8/18/92 SET 1" SQ PIPE/CAP AT LOCATION OF CIM SET IN 1976 BEFORE ROAD GRADING. THE CORNER FALLS 7.8' SOUTH OF & C.R. #12
RP's CSD IN PP # 44622 SSW 48.95'
CHD DISK IN PP # 49349 NNW 61.89
5/8" ROD IN CROP LINE SOUTH 107.31'

6-2-76 Set CIM

#830706

Form. 10R-13

¼ Corner W.¼ 7 - E.¼ Cor. Sec. 12 - 10R-14

Cor'T notes: Oct. 1853 John Ball Deputy.
40.00 Ch. Set post for Qr. Sec. Cor.
Burr oak 10" N 80°E 142 lks
Burr oak 10" N 3°W 287 "
47.00 Enter timber bears N.W.
55.00 Enter Prairie NE

6-2-76 Dug 4' diameter around corner post to 4-way fence. Found nothing. Set CIM over 1¼" x 24" pipe at corner post to fence N-S-E-W.
R.P.'s: Spike and CSD in blazed 4" tree NNE 29.55
Spike and CSD in N side blazed 5" Boxelder WSW 16.55