X 5-28-76 Set CIM #830805 (1)
8-7-80 set "Shorty" C I M. over original C.I.M.
section corner 7-8-17-18 Farm. 108-13
5-1878 Hunter P 347 no 340 S 17. W Taylor, N Schacht.
corner gone. on anors of Mr. W H Murry J. Carsten.
owner NE¼ 18 that his fence west was on line
and his fence on west side of road was 40' reset
corner set stone 4x12x12 as corner. Road fences
running north also proved corner correct. in center road.
- meas east 39.76
- meas south 39.98½.

6-1879 Hunter P 364½ no 352 S 18 H Buchholtz.
C Bluhm & others.
found stone center road. P 364
(over)

Meas south. 39.98½ to stone.
Meas west 39.95 to stone.

5-1895 H Fraser P630 no 570 & H. S Martin, Wagnor.
found stone P347.
-16 south set small stake N & L 19.97

Corner now ¾" rod & old 1" pipe & 63. origin unknown.
Spike power pole. N.W. 131.17. ?
Disc " " SW 47.42
NE corner of gas station office SW 144.15
-7-21-1970 Co surv. corner not preserved evidently in old road surface about 5.5' deep - gas station office only remaining RP state shows new center line 1 which with PP
N very near 131' unmarked but a spike/nail low on E side could be same job

#830805 (2)

Section Corner 7-8-17-18 Farmington 108-13
Set by William Yerby 5-1854

80.00 Set a chared Sec post in a mound for Cor. to Sect. 7,8,17,18 & made trench & pits & planted Osage Orange Seed on NE & SW. sides of trench.

5-24-76 Dug with backhoe and found 2 limestone side-by-side with pottery around 9' deep. One stone 4" x 0"/10" x 14". The other on SE side was 4x10x12. Put junk around stones and drove 4' piece of pipe (with elbow) along side. Corner 4.1S and 2.4 E of traverse nail and 1.65 S and 1.5 E of Mn. Hwy Dept. hub found. Corner 3½' S of ℄ E-W road and 39.6 W of ℄ T.H. 63

R.P's: pp # 34981 - CSD NW 135.6
concrete mail in guard post SW 28.70

7.23d

NW corner of garage on gas station SW
CSD pp # 34980 SSW = 174.60
CSD pp # 40301 NE
Punch mark top lug nut S. end 24" CMP to road E SE
Chisel X top N end 24" concrete culvert to road E NE

don't take

5-28-76 Set CIM over 5/8" x 18" rod
8-7-1980 (1980 Remon BK) Sec. Cr 7-8-17-18: Found CIM 11" deep after T.H. 63 overlay. Set 10" CIM over the CIM in place.
7-16-1984, Sec. Cr 7-8-17-18: Took reference before road graded.
Occupied Pt Reinkei Corner (1" sq pipe/cap in bituminous in NE cr intersection TH63 and T.H. 247) and turned ∠ Rt 160°52'34" from 1/4 Cr 8-17 (1/2" pipe 1' So of TH 247) to CIM @ Sec. Cr 7-8-17-18 and meas. 72.39
(See Farmington Twp BK 4 more info on intersection

✓(830805)

7-26-99
MW, RF, AE

Sec Cor. 7-8-17-18 108-13 Farmington Col
Found CIM 1" deep in blacktop
at Int TH 63 & CR # 12
39.6' West of ℄ T.H. #63 &
3½ South of ℄ CR # 12
Pin pointed REINKE (1" SS pipe w/Cap)
with metal locator. This pt used
as Ref to Sec Cor in (1984)