X

#831406 (1)

1/4 Corner. 14-15 Farm 108-13.
Set by William Kerby 5-1854
9-1894 H F Fraser. P552 No 509 S 14 K Lampreakt
Corner could not be found, but Mr H Schacht avers
he set fence running east on direct line and corner
post 33' east of corner stake when standing.
- set boulder on line fence east and 33' W of cor. post.

5-1900 Ch Armstrong P668 No 593 S 15 A Kruger.
used corner not mentioned only the center was
set at intersection of all right lines.

over.

Co Hwy Dept. B 199 P 5 found boulder 2 1951
stone 6 x 8 x 15 found - set 1" drill steel riser 1961

Sp	fence post	witness 1961 tie	E.N.E	~~gone 22'~~ 55.45
"	"	"	S W	~~40 E 92'~~ ~~86.65~~
"	power pole		S E	91.15

Meas south 2629.3
Meas north 2630.6

Co H D 5-1932 B 67 P 12. found stone boulder 6 x 8 x 15
corner a P I ∆ 0°03' left going south. Sta 26+64.3
Meas south 2629.9. Sp in Maple S E 45.95, Sp in elm E 33.13.
Fence post W 28.6 Tele P S W 47.3
Corner lines fences east & west.

#831406 (2)

1/4 Corner 14-15 Farmington 108-13

40.00 set a qr Sec post in moond of Earth & Sod deposited charcoal made trench & pitts, planted Osage Orange Seed E & W.

6-15-93, 1/4 Cor 14-15: Found CHD drill steel down 3", 1' West of ℄ N-S C.R. 11 and in line fence East and West. Set nail @ rock surface over iron.

RP: CSD N. side C.P. West 48.81

Ck CHD nail NE side (down low) pp # 35180

SE 91.18

7-29-93, Set 1" SG Pipe w/cap ~~RR~~ 179°59'28" to P.P. w/Pk Nail in North face. The Ref Pipe w/cap is on

over →

South edge of 2nd Driveway of 10924 CR #11 NE ± 30'
East of ℄ CR #11 ℄ ± 7' So. of ℄ Driveway.
¼ Cor 14-15 Drill steel (lower half drill steel tap down 10")
To Ref Pipe w/cap

VA 90° 37' 26"

Slope 239.07 Hor 239.06

7-8-94 SET 1" SQ PIPE W/CAP @ 1993 REFERENCED LOCATION OF DRILL STEEL. THE CORNER IS ½' WEST OF ℄ CR #11 + IN LINE OF FENCE WEST. ~~CSD IN C.P. WEST 48.81~~
CSD IN C.P. WEST 48.81