X 5-26-76 Set CJM #831705 (1)

section corner 17-18-19-20 Farm. 108-13
1-1878 Hunter P 327 No 321 L 19 H. Blohm, t others did not look for corner, but Wm Blohm anera he and others set a stone a foot below surface before road was worked where old stake stood and it was still there.

5-1878 Hunter P 346 No 339 L 20 M. Bennick, Mike Kulyman found stone in center road as claimed P 327.
-16 south set stake, well down, M & L 20.00
- meas east 39.95

5-1878 Hunter P 347 No 340 L 17. W Taylor, Schacht found stone P 327 - P 346. (one) L Easton

-16 North, set stone N & L. 19.99 1/4
staked line for fencing east & above 1/16 corner
- Meas east 39.9 ft

6-1879 Hunter P 361 No 352 & 18. A Buchholz
found stone P 346. C Blohm & others.
-16 North found stone N & L. 19.99 1/4.

4-1919 Ch Armstrong P 318B & 19 & 20 W Blohm.
found boulder. 5 x 12 x 23 in center crossroads N-S-W.
- Meas south to iron set as 1/4 cor. 2622.

~~Mound Hwy Dept~~ MCoB 1954 found 5"x8" topped stone down 3'.
Sp in power pole. W 62.67. SW cor Mach Shed.
SW corner granary & SE 162.25' & SE 119.65
" " corn crib " 142.7 E 1/4 Cor. 18 info.

#831705 (2)

Section Corner 17-18-19-20 Farmington 108-13
set by William Yerby 5-1854
80.00 set a chared Sec. Post in mound of Earth & Sod for Cor. to Sec's 17, 18, 19 & 20 & Made Trench & pits & planted Osage Orange Seed on NE & SW sides of trench.

5-26-76 Corner comes in deep cut area of T.H. #63. Reset Corner at double line and measure from Sec. Corner 7-8-17-18 (found) over 1/4 Cor. 17-18 (found) as per T.H.'s Survey # 340 P. 347. Set CIM over 1¼" x 12" pipe. Corner in ℄ T.H. 63 and 1' S ℄ road W and 1' S line of fence E.

R.P.'s: Punch mark in lug nut top N end CMP to rd. W NW 44.06
Punch mark in lug nut top S end CMP to rd. W SW 44.54
CSD in power pole SW 88.28
CSD in new corner post (on E side of old one) E 75.60

(831705) - T=75°
P=29.1

7-26-99
mw RF AE 59

Sec Cor 17-18-19-20 108-13 Farmington

Found CIM in good Condition 4" deep in Blacktop TH #63 Referenced before Cold Recycling & overlay project Set 1" sg pipe w/ Cap on South edge of 105th St NE 16' South of ℄ 105th St NE and 80' West of ℄ TH #63

TC@ Ref pipe
4 Rt PK in PP # 43575 to 17-18-19-20
176° 47' 14" dh 02 178° 12' 53" dh 03
0° 01' 07" dh 02 1° 26' 47" dh 00
176° 46' 07" 176° 46' 06"

3 Rt Top Center Silo SE of Hoeft Largest Corner to 17-18-19-20
289° 16' 36" dh 02 286° 31' 01" dh 00
3° 02' 22" dh 00 1° 16' 43" dh 02
285° 14' 14" 285° 14' 18"

To Sec Cor 17-18-19-20
VA 90° 13' 28" dh 05
Slope 82.785 Hor 82.785

Removed top 10" of CIM. We will be able to set 12" pipe after B.t Project.