10-13-1965 set CIM over 5/8" rod. by meas & line #832005 (1)
section corner 19-20-29-30 Farm. 108-13.
4-1875 Hunter P268 No 266 S 29. L. Greenwood
found short stake in center road in line fence south.
- meas south. 39.99 to stone set M & L.

1-1878 Hunter P327 No 321 S 19 H Blohm & others
found stake center road with stones around it
50 lks from south road fence in line fence south.
-16 north set temp stake M & L 19.98½.
-16 west set stake M & L 19.76
-16 center SE¼ 19 set stake inters lines
staked all lines for fencing.

5-1878 Hunter P346 No 339 S 20 M Bennick, M Kalymax
found stake & stones P327. over.

- Meas east 40.01 1/4 to stone 1½ x 5 x 14 set M & L.

3-1879 Hunter P 355 No 347 & 30 W. Spring, P. McKee.
found stake & stones P 327.
-16 west set stake M & L 19.78
-16 Center NE 1/4 30 set stake M & L 19.97 N-S 1/16 line

4-1919 Ch Armstrong P 318 B & 19 & 20 W Blohm.
Corner in deep road cut, now near bed rock,
26" ash tree 70' south & west of sec line.
took east edge of tree as line - fence south gone also.

10-1965 J Kerr.
dug for corner twice found evidence that road really was a deep cut, real deep dug 4 to 5 feet deep.

See No 2 Card.

#832005 (2)

second card on corner.

Section 19-20-29-30 Farm 108-13.

Meas line from West section corner of 19-30.
east.

- found 1/16 fence east at 1132.8 set 120 D.
  corner finally fixed at 1134.2.
- 1/4 cor 19-30 set 120 D by meas 4' south corner
  past (no line). under fence at station 2447.8.
  corner finally fixed at 2438.4.
- meas to above section corner fixed at 5046.78.
  making 3 1/16 corners at 1304.2 then 1134.2 to Sec Cor.
  record. claims 1305.2' then 1135.5'

(over

This makes meas east 5279.0 to 20-21-28-29.
record 40.01½ or 5282.0 " "
" it was found that fence line south at ¼ 20-29.
corner set M & L was way short on east end.
Armstrong gives meas of 2617' to fence North. and
no meas there west. sec ¼ 20-29.

10-13-1965 set C/M in center road. at distances given
- center east end of 12" field culvert NE 31.6.
- Rec in tele pole. ~~NE 39.5~~ gone 1983
- Rec in power pole. ESE 93.2.
- Co Hwy Dept 40D nail in center U863 E 636.65.

this nail is 4.8' south of section line set up.
Must find stone at ¼ 20-29 to prove line exactly.

Section Corner 19-20-29-30 Farmington 108-13 (3)
Set by William Yerby 5-1854 #832005

45.00 Ascend a Bluff, leave Bottom ∠ to E & SW
55.00 To top of same Bluff & descend
57.50 To foot of same Bluff & ascend
60.50 to top of Bluff
65.00 descend same Bluff Left bottom E & SW
73.00 To foot of same Bluff.
80.00 set post - corner to Sect. 19, 20, 29 & 30 in mound of Earth & Sod deposited charcoal made trench & pitts planted Osage Orange Seed NW & SE

5-7-76 Dug 4½' deep on S. side of Rein CIM. Found nothing. Very poor condition.



6-14-93, Sec. Cor. 19-20-29-30: Found CIM OK, down 5" in E-W cracked rock road, 1½' N. ∠

RP's: Old CHD Disc in N. Side pp # 34846 SE 93.30

MHD Disc in N side pp # 34846 SE 93.43

Punch hole top E end CMP in Field drive

NE 30.52

Flange of channel iron survey marker sign post

S. 34.51