/ 5-27-76 Set CIM #832006 #1

1/4 corner 19-20 Farm. 108-13

1-1878 Hunter P327 No 321 & 19 W Blohm & others found unmarked stake in center mound in line of fence running North, east & west.
-16 south set temp stake M & L 19.98½ for line W.
-16 west set marked stake M & L 19.91 (1314.06' for line S.
-16 center of W ¼ 19 set stake at intere 1/16 lines.

5-1878 Hunter P346 No 339 & 20. M Bennick, N Kitzman found stake in mound P327.
-16 north drove stake (well down) M & L 20.00

4-1919 Ch Armstrong P318B & 19 & 20 W Blohm.

- run line from known NE cor 19 south to east side of 26" ash tree averred to be in that location from orig cor.
- Enter this straight line with E-W 1/4 line 19. from Center 19 over 1/16 east, points set by Hanter (claimed).
- set iron bolts at Center 19, 1/16 east and 1/4 19-20.
- 16 north fence line east at 1311'
- 16 west found iron bolt at corner east & south fences.
- RP 1/4 19-20. 9" birch tree N 90° E 94'

Set by William Yerby 5-1854

33.00 Begin to Ascend Hill or mound E&W
39.00 Top of Hill
39.50 Begin to descend Hill
40.00 set a chared qr post in mound of Earth & Sod made trench & pits & planted Osage Orange Seed on East Side of trench.
46.00 Foot of Hill.

#832006 #2

¼ Corner 19-20 Farmington 108-13

3-31-76 Found C.A.'s iron (1") under E-W fence 38' E of corner post to fence N-E-W

5-27-76 Drove iron found down and set CIM over. RP: Spike + CSD in 8" cedar ESE 25.1'
CSD S. side of corner post N 38.00