10-12-1965 set C/M over 5/8" x 19" rod with (1)
2x6x8 limestone on N side and 3 flat iron fastened together
on south side, broken glass at bottom #832106

1/4 corner 20-21 Farm 108-13
5-1878 Hunter P346 No 339 L20 M Bannick
Corner completely gone. no knowledge M Katzman.
except that 1/4 fence west seemed to be straight across
section. Meas N-S section line and found fence very near
midway. set stake on line E-W fence. likely 4 rood.
-16 south set stake M&L 19.96 1/2.
- meas north 39.96

5-1900 ch Armstrong P666 No 592 L21 J Thoming
Could not find any trace of corner. (over) J Welke

set boulder stone 6X7X10 M&L 40.01 1/4.

4-1919 Ch Armstrong P 318 B L19 & East side L 20.
Plat shows stone & iron bar 2617 North of the SE corner
Section 20 which doesn't jib with even his own work P666.
H Blohm.

70-1965 J Kerr.
Meas from NE 17 to SE 32 4 miles. set NE & SE
corners 20 dug 4'x5' hole looking for Armstrongs stone.
Mr Thoeming remembers old survey, said road shifted east
corner destroyed by mucker grader set corner M&L 2633.5
- set C/M over 5/8 x 19" rod with stone & irons & glass.
- hub nailed to SE side 14" spruce Most southerly NE 56.6
- Pine NE side tele pole with control box on W side SE 62.85
- corner lies 13' west of center road - 3' off W side road edge.
- corner lies .6' south line of steel posts east.

#832106 (2)

1/4 Corner 20-21 Farmington 108-13
set by William Yerby 5-1854
40.00 Set a chared stake in mound of earth & sod. made
Trench & pits & planted Osage Orange Seed on E-W
sides of trench.
50.00 leave dry prairie bottom. E & W.