8-1-1961 CIM over rod — set by county. ①
6-28-1974 reset C.I.M. over ⅞" ø 18" rod over stone
section corner 21-22-27-28 Farm 108-13
5-1900 Ch Armstrong P666 No 592 S21 J Thoeming # 832205
dug 2' deep over 10' area & found nothing. J. Thelke.
set stone 4x12x22 after meas
NE cor 16 south to SE cor 28 and.
SW cor 21 east to SE cor 24.
- meas west 80.21
- " east 80.20
" north and south 19.98.6.

over.

Co Hwy Dept | B 238 P 2. 9-13-1960
6-8-1961 set CIM
found & used stone and on completion of new grade
set C/M in place of corner preserved. 8-1961
Hub in fence line NE 9628. OK
Dicc power pole. NE ~~61.83~~ 6193
Dicc tele pole. No.We 529. OK
Dicc nail in P.P. — S.E. — 59.7
Meas west 5285.48
Meas. east 5283.54

set by William Yerby 5-1854
80.00 set sec post in mound of Earth & sod deposited
charcoal made trench & pits, planted Osage Orange Seed
NW & SE

#832205 (2)

Section Corner 21-22-27-28, Farmington 108-13

6-14-83, Sec Cor. 21-22-27-28: Found CIM down 3" in ℄ blacktop C.R. 21, and in ℄ crushed rock road South and 4' West of ℄ crushed rock road North.

RP's: CSD in NW side pp# 20004 NE 61.67
(old CHD disc in pole)

CSD in SW side pp# 20005 NW 52.82
(old CHD disc in pole)

CSD in NE side pp# 42443 SE 59.80
(old Nail in pole)

6-21-93 Set 1" SA pipe w/cap on line to CSD in So. Face 4th P.P. North of Intersection of Roads. 118.04' from Lot to Corner.

VA 92° 43' 56"

Slope 118.17 Hor 118.04

7-14-94 SET 1" SA PIPE W/CAP @ 1993 REFERENCED LOCATION. THE CORNER FALLS IN ℄ CR #21 + ℄ TWP RD SOUTH + 3' WEST OF ℄ TWP RD NORTH. THE CORNER FITS THE 1983 TIES TO PP's NE + SE. THE NW TIE IS NOW A NEW POLE.