#832304 (1)

NOTE: See Unfinished corr file

1/4 Corner 23-26 Farm. 10 8-13.
Set by William Kerby 5-1854
No records.

Co Hwy Dept

1"x 2' pipe as corner. set M & L.

Spike	corner fence post	S	25.5
"	power pole.	SW	41.5
"	tele pole.	N	40.7
West gate post cemetery		SE	64.2

∴ Meas east & west 2639.35.

Exact Ker. data B32 P28 10-1946. set at that time

39.99 Set a g r see post in mound of Earth & Sod deposited charcoal made trench & pits planted Osage Orange Seed N.E.S.

¼ Cor. 23-26, 7-25-83: Dug with jackhammer in E road appx 2' West of the fence South. Found 60d spike down 1'. Found a 40d spike slightly deeper and .2 E. ~~The~~ Clean clay down 1½'. The road surface here is in a cut being 3' below top of backslope of ditch on the South side of the road (out 37') and 1' below top of backslope of ditch on North side of road (out 50')

8-4-83, ¼ Cr 23-26: Set a CIM over a 3/4" x 18" rebar at CHD 60d location. Could get rod dip at Kerr's location 7.6 So. and found 4.8 E. of CIM.

RP's: Punch hole in East end 18" CMP NE 53.66
Punch hole in West end 18" CMP NNE 35.02
CSD in pp# 19969 South 57.43

#832304 ②

1/4 Corner 23-26 Farmington 108-13

6-22-93 Sighted Radio Tower SW Turned 180° & Rt and set 1" Sq Pipe w/cap as Reference 61.93'
VA 91° 16' 02"
Slope 61.95 Hor 61.93
Ref Pipe is ± 8' East of E Field Drive & ± 50' North of E CR #21.

7-15-94 SET 1" SQ PIPE W/CAP AT 1993 REFERENCED LOCATION. THE CORNER FALLS IN E CR #21 + 1½' WEST OF FENCE LINE SOUTH. THE CORNER FITS ALL OF THE 1983 TIES.