#832306 (1)

1/4 corner 22-23 Farm. 108-13.
Set by William Kerby 5-1854
no records.
Co Hwy Dept B199-
found boulder set 1" drill rod riser. (1961)

Sp	fence post	W S W	51.98
"	"	E	51.51
"	cor "	W	49.5
Hub	in fence line	W	82.89

10-1946 Cen Book 36 P 29: Found Cor

Meas south 2639.6
Meas north 2639.3

Co HD 1932 B67 P14. found boulder & pipe

Sta 79+36.3 a P.O.T. going south.

40.00 set a gr see post in mound of Earth & Sod. deposited charcoal made trench & pits, planted Osage Orange Seed E & W.

44.50 Enter "Wet" Marsh bears NW & SE

45.50 leave Marsh " " " "

6-14-53, 1/4 Cor 22-23: Could not get good enough dig to pickhammer corner. Could be something deeper. Only CHD R.P. remaining in fence post West with small spike, probably CHD's, Hub 52.5 West could be there, but not us.

7-12-83, 1/4 Cor 22-23: Dug from the t.n. set in the E. C.R.11 and in line with the fence West, West 2', East 2', North 3½', and South 4½' by 5½' deep to green clay. Under the blacktop found a 10" long drill

#832306 (2)

1/4 Corner 22-23, Farmington, 108-13

7-12-83, 1/4 Cr 22-23 & ~~Sec~~ Continued) steel .54 South and .75 East of the t.n. Down 1' found 34" drill steel .59 South and .66 East of the t.n. Down 3½' found a 7/8" x 31" rebar bent North, .53 South and .33 East of the t.n. Down 5½' found a boulder 8" x 12" x 12" with pointed top .52 South and .28 East of the t.n. There is appx 1' of black dirt here but it is ~~sandy~~ harder and more mixed than we have found so far on this road. The top of the boulder was beneath the black dirt and the bottom 1' down into

the green clay. The top ½ of the stone has been dug around (probably by CHD), but on removing the stone could find no evidence that it had been dug ~~around~~ in. Believe this stone only a subsoil boulder that coincidently happened to be in the center of the road and in line with the fence and having a point up may have looked like a corner when digging by hand down on stone from above. Set a ½" re-rod back at the road surface at the stone location to maintain CHD PI loc.

RPs to ½" rod;
Probably CHD nail in c.p. (leaning W.) W 49.75

t.n. } N. 6.92
W 5.45

Removed stone and all other iron found. See Remon. BK
For locals to pttc Fd)

#832306 (3)

1/4 Corner 22-23 Farmington 108-13

7-30-93, Set 1" Sq pipe w/cap west of corner near R/W fence as Reference. The Ref pipe lines w/fence west ± 45' west of ℄.

↑ @ Ref pipe

x Rt Top center silo NNW to 1/4 22-23 100° 42' 49"

VA 88° 24' 18"

Slope 46.00 Hor 46.00

7-8-94 SET 1" SQ PIPE W/CAP @ 1993 REFERENCED LOCATION OF 5/8" IRON IN ℄ CR# 11 + IN LINE OF FENCE WEST + 2' NORTH OF FENCE LINE EAST.

R.P.'S 1" SQ PIPE W/CAP WEST 46.00