~~8-1-1961 C/M over iron, set by Co Hwy Dept.~~ E 24-25 #832404 ①

¼ corner 24-25 Farm 108-13
Set by William Verby 5-1854
11-1877 Hunter P 323 No 317 S 24 L De Witz.
found stone set in center road by adjacent land
owners where orig cor stood.
– Meas east 39.96.

Co Hwy Dept. E 24-25
2x2 hub over iron Likely assumed, set C/M over iron

Disc	fence post	NE	54.12
"	power pole	NW	62.63
"	tele pole	SE	42.1

40.00 Set a gr sec post in mound of Earth & Sod deposited charcoal made trench & pits planted Osage Orange Seed N & S.

6-14-83, 1/4 Cor 24-25: Dipped in ℄ E-W C.R. 21 and in line fence N & S but could get no dip of CHD CIM. Don't believe card on this.

7-18-83, 1/4 Cr 24-25: Dug from a point 9' West of the t.n. set in ℄ road and in line west fence North and South, West for 8't, North 2', and South 4' by 8' deep to clay. Black dirt down 6½ to 7 feet. Very good condition but could find nothing. Probed all around hole. Finally hit stone 2½' North of the North edge of the hole. Found mark of stake on North side of stone. Set 3/4" re-rod at stake mark and set stone back on South side of rod and a piece of blacktop on South side of stone. Stone 3½" x 7" x 15" and split in two piece, down 6½'. Diggings on T.H. mean from E and line from North

#832404 (2)

1/4 Cor. 24-25, Farmington, 108-13

8-8-83, 1/4 Cor 24-25: Set a C.I.M. over a 3/4" x 18" iron over corner found 7-15-83. The corner is ± 4' North of the ℄ of the E-W road and ± 14' West of fence North and South.

RP: CSD in pp# 19948 NE 40.08

8-3-93 Set Ref pipe w/cap NE of corner. The Ref pipe is 40' North of ℄ CR # 21 & 10' East of fence line North

T@ Ref pipe w/cap ∡ Rt Tower with light on top SW of corner (not tower to south of corner) to 1/4 cor 24-25
344° 58' 58" VA 92° 10' 48" Slope 45.58 Hor 45.54

7-18-94 SET 1" SB PIPE W/CAP @ 1993 REFERENCED LOCATION.
THE CORNER FALLS 4' NORTH OF ℄ CR #21 + 14' WEST
OF FENCE LINE NORTH + SOUTH.