#832505 (1)

7/20/83 Set C.I.M. over Hunter iron
~~11-20-1963 set C I M over limestone~~
10-5-1972 found iron stake set by Hunter 1886.

Section corner 25-26-35-36 Farm 108-13
Set by William Perby 5-1857
11-1886 Hunter P 416 No 405 & 36 N Lode, E Raymond.

Corner gone run corner in by meas, drove iron bar as corner which came in center crossroads. drove iron deep

- Meas line N 1/4 31 108-12 to NW 35 108-13 short 22 lks for 2 1/2 miles. Govt 37.30 - 80.06 - 79.88. 2461.8 5283.96 5272.08
- Meas line 1/4 35-36 North to 1/4 25-26 short 7 lnk
- Meas north & south 39.96 1/2. 2637.7
- Meas east ~~39.98~~ 39.98. To 1/4 25-36 set 2638.68
- Meas west 79.80 (5266.80
- Meas last (mile 79.96 (5277.36

(over

limestone with pipe user used as corner.
11-1963 J Kerr set C/M over limestone.
Sp power pole 35.96 } 10-5-72
" " " 127.05 }
" tele " 66.15

NE 43.20
E 122.1
W 39.5T

- meas North 2640 to midway R 2637.7
- meas west 2630 to M&L R 2638.7.

Could be iron rod still in place some distance east could be proven by meas 2 miles as in P 416.

B 328 Co HD 1967 found C/M but no meas to it.
Meas west 5258.9 to 00+00 Sp Cor FP N.W. 54.07 C/M RP added
- Sta PI 52+59.39 - RPI Sp D PP NE 42.77 Meas E
Sp D Cor FP NW 52.76 - Sp D TP SW 39.94 as 1/4 25 T36

#832505 (2)

Card # 2. 25-26-35-36. Farmington 108-13
10-1946 JKell Book 32 P 27.
found large limestone set. pipe near
43.5 NE to sp in PP
122.0 SSE To Sp in PP
41.2 SW to Sp in T.P
North. set 1"14 "x 30" pipe N & L 2640' which came
3' S of fence west and 22.3' E of "F." likely road fence.
did not evidently search for Hunters. "1/4 post."

9-12-72 ran line and elec meas from C/M at
E 25-36 direct to C/M in place at above corner.
"C/M at E 25-36 had wet land tombs and was
tilted NNE well over a foot - dug to stone below and reset
(over

found meas ¼ mile to be 52.75.39 R 5277.36
in 6-1966 East line of NE ¼ 36 meas. 2638.9± R 2640.66
so this meas indicates NW 36 may be in error.
- found meas to fence S at ¼ 25-36 at 2646.83 R 2638.66
- found meas S to fence E (not W) at ¼ 35-36 at 2622.28 R 2637.7
Eugene Hunters Quote "drove an iron rod at said corner
the full length into the ground" unquote.

9-26-72 dug from C/N north at least 6' north covering area
3' west +, 3' east + to clay searching for some trace of
Hunters iron or rust hole. exposed stone found by Ikerr.
on super clean soil at least 12" wide 14" high and quite thick
very vertical and well placed
9-27-72 dug massive hole at ¼ 25-36 and found nothing
so did not prove or disapprove above section corner.

Card #3 25-26-35-36 Farmington 108-13 (3)
10-5-72 dug again more Northeasterly and easily found Hunters iron bar 3/4" round rod with at least 2' lying bent flat and considerable amount stub in ground very vertical and solid. - Rod found 4.34E, 5.94N by true transit reading from line east. #832505 angle N to E not taken at this time. - Referenced now only
35.96 NE to disc & nail with Cone nail above nail on SE side power pole. former 43.5
66.15 SW to cone nail in small knot on E side Tele Pole.
127.05 SSE to center no plate 1980 on W side P.P.
- found 1/4 25-26 3,4E 2.26N R. 5277.36 5275.06
final Meas. 2635.29 N. - 5271.05 E. - 5268.06 S.

Nail south set on direct line between C/Ms at.
S 2629.98 - N 2632.14. must now move north.
2632.14 + 5.94. = 2638.08 - 2635.29. or north 2.79'
-direct line to rod from C/M at S 35-36 would now pass
2.17 ± east of nail. final setting ¼ corner as follows =
10-6-72 set C/M over ¾" x 20" iron at ¼ 35-36
6.16 west 2.79 north orig nail of 8.33 W direct line
meas N 2635.29. to iron rod which is referenced only.

Summary of 2 corners at 25-26-35-36
C/M left as is - iron covered & referenced R 2638.68
- set C/M east at 2635.52 M & L betw. iron and C/M at E. 25-36
- set C/M South at 2635.29 which is same meas as iron N to
stake found. as recorded. Norman R 2637.7

80.00 Set post Cor to sec. 25, 26, 35 & 36 made a trench
Br Oak Tin. S45°W 2.06 lks.

#832505 (4)

Sec. Cor. 25-26-35-36, Farmington, 108-13:

7-20-83, Sec. Cor. 25-26-35-36: Set a CIM over a 3/4" x 18" re-rod as the corner at the location of the iron found by Roger in 1972. 5.94 North and 4.34 East of CIM set by John Kerr (removed). Corner 4' North ℄ E-W road and 6' East ℄ road North and 3' East ℄ road South.

RP: CS Disc in SE side power pole NE 38.64
concrete nail in SE side telephone pole SW 66.25
CS Disc in W. side pp# 19801 SSE 126.93