X

#833504

1/4 corner. south 1/4 35 Farm. 108-13.
north 1/4 2 Haver. 107-13.

5-1872 Hunter P202 No 211 S1&2 J Moody;
A Raymond.

Corner missing. NE BT cut, other BT standing
set temp stake from BT for line south. No meas.

7-1966 J Keir.

Corner could not be in place. deep ravine just
north of road in area of corner deep fresh fill.
- run & meas line from S W 35 to S 1/4 36 from
Cover

last. Misjudged line so random came over 2 rods south at west end. this bringing corner at S ¼ 35
3' off road on north side traveled road in soft fill.
- Corner placed a ½"x 4' rod on M&L. 2630.85
- corner lies 3' west of fence running south.
- drove ½"x 3' rod up 3" on west side fence S. 100.0
- Pole south side large trans power line ENE 178.8
- 4' rod may not stay in soft new fill, C/M would never.

Set by John Ball 10/18/83
11.90 Brook 3 links wide Bears North
40.00 Set post for qr. Sec. Cor
Burr Oak 6 N 88 E 670 lks.
Burr Oak 10 N 80 W 280 lks.
60.00 leave opening center prairie bears NE
69.20 Brook 3 links wide bears NE