/ 9-27-72 dug entire area found nothing, set nothing
10-6-72 set C/M ovl 3/4 x 20" iron by meas. (1)

1/4 Corner 35-36 Farm 108-13
#833606

11-1886 Hunter P 416 No 405 S 36 N Lake, E Raymond.

1/4 corner gone - reset from SE BT still standing
Reset corner also set stone as witness 2 rods east.
-16 east set stake M & L. 20.02/3
- meas south 40.00
set stakes from corner south at following spaces
in chains 5.00 = 5.00 = 10.00 (1/16) 2.50 = 7.50 = 10.00
- meas North 39.96 1/2 which is midway to 1/4 25-26
2637.7

Corner

7-1898 H Fraser P 639 No 575 SW¼ S36 F. Kefer

found witness stone P 416. R Moody.
set small stake 50 links west to use as corner.
-16 south set stone M & L. 19.98.
-64 south " " " 9.99 from ¼ cor.
-16 east set stake M & L. 20.02 a stake by Cor. post.

Corner area now in deep cut very much ledge rock.
No chance of witness stone surviving. - Could meas from E.
9-27-72. dug a little west of nail set on transit line betw section corners set 9-12 in line fence east, also at 1/16 area south, in both cases topsoil as rocky fill & green clay all mixed from top to bottom. station of nail in line fence east and on transit line N & S section corners North 2632.14 S 2629.98

#833604

Card #2 1/4 35-36 Farmington 10 8-13 (2)

10-5-72 found recorded stake at 1/4 25-26 recorded as used to set 25-26-35-36 equal meas from 1/4 35-36 and it - also found iron rod set by Hunter 11-1886 used above. - after final comp. set C/M over 3/4" x 20" rod below. at 2635.29? north 2632.77 south 1321.4 east. -16 E set 1/2" rod as final E-W subject to meas South. of 658.46 to 1/64 corner after correcting it about .5 south. - left Lw 36 C/M set by J Kerr 1966 as is. - meas north to rod found. Nat C/M as still in place - Rod there less 5.94 north 4.34 east of stone 2nd C/M.

1/4 35-36 a hopelessly lost corner replaced after 3 weeks work ± per RPS

RPS to C1M set as 1/4 35-36. set 10-6-72.
Corner very near line fence west, 3' N fence east ±.
NO. 3 SE to pipe cap SW side PP# 19787 level mea.
OK 1983
32.95 SE to cone nail in top corner post
32.98 1993
60.5 E to 60 D N side 12" oak level mea (not slope)
60.6 1983
60.8 W to 5/8" x 13" rod under fence. level mea. SE fence
60.1 1983 corner west of center road 2'±
Corner as set. 6.16 west of direct line of C1M s.
8.33 west of direct line C1M at SW 36
and iron found at NW. 36
2629.35 N to C1M. set 1963 and left as is.
2635.29 N to iron rod set 11-1886, found.

1/4 Corner 35-36 Farmington 108-13 (3)
#833606

Set by William Yerby 5-1854
15.00 enter B/k O. grove E & W
26.00 Enter Prairie E & W
40.00 Set a qr sec post
Br. oak 8in S 82½°E 148/ks
Br oak 8in S 34°W 297/ks.
46.00 Stream 5/ks wide N.E.

6-13-83 Found 28" Burr Oak ESE wheel pits Cor
Brg and distance to CIM set by County
Surveyor in 1972