8-14-1964 set C/M over 1"x14" steel rod.

(Questionable Corner -- 1-31-1978 LB.) #840109

¼ corner Center 1 Aronco 108-14.

5-1879 Hunter P359 no 350 S1 L Pomray, A Stedman.

set stake with stone by its side at true intersections.

-16 east set stake N M&L 20.01 27½ line north.

-16 south set stake N M&L 19.78 27½ line west.

- meas west 39.85

1964 J Kerr run N-S ¼ line

set C/M in place of corner found earlier survey.

long boulder, steel rod, chockery etc. (see Kerr BE-6 p 9-14

placed 1"x14" rod below C/M. center set M&L on E-W ½

corner lies 1' west of fence corner.

corner lie 2' " " 8" burr oak tree.

corner lies north of buildings in hollow. and couple

hundred feet ~~West~~ of winding road - over -

there is steep road cut bank between road and corner and brush.
- fences run west and north, not too new.

1946 C H D B 144 P
Meas 2609.1 N'41 south to center 1. random.

Jan. 10, 1974 Co. Surv.
Inasmuch as the electronic Trav. meas. was over T. Hunter's Mons from W.¼ 1 To Center, We dug hole on W. side of existing Mons. (dug from 1' N. of Mons. To 7' W. & about 2' N & S of fence running west.), did not find Hunter's Stake with stone by Side. This existing corner could have been found or Set by J. Kerr in 1925 (B.-6 P.13). Since Nothing would be gained by Moving this Corner, we decided To accept it and use it to Set S.¼ 1. PR