~~7-7~~ - 1964 set C/M one 1" x 30" rod. #840204 (1)

¼ corner 2-11 Oronoco 108-14.

12-1895 H Fraser P 586 No 534 L2 C Isaco, F King. C Kurth & others.

corner came in cultivated land and ~~last~~,

set stone N & L. 39.52.

-16 west set stake N & L 19.76 (1304.16'

-16 north " " " 20.04 in lake.

-16 center SW¼ set stake intersections.

-64 south center SW¼ stake N & L 10.03

-64 west " " " " 9.87½

- meas east 39.52 (2608.32'

5-1900 Ch Armstrong P 668 No 594 L11 Fred Koenig.

found stake and stone P 586.

- meas east & west 39.52 probably expand 4.00 W.C.K. added

-over-

-16 south stone 8 x 10 x 14 made mound ~~x~~ pile
5" burr oak S 57° W 14 links. - 10" Jack Oak west 7 lks.
stone M & L 20.10

10-1939 J Kare. P518B B16P33. Ch Bell.
found & used stone.
Meas east 2596.05

7-1964. found stone 9 x 9 x 35 with cross.
set C/M one 1" x 30" rod.
Nail in hub in 18" twin red oak NW 52.12.
" " 12" " " " E 33.15.
new steel fence post NW .7'
crushed rock around top of corner Lastud E 34.33
20 D nail S Side center punch up 2' same tree

Card # 2 1/4 2-11 Orno 108-14

#840204 (2)

1939 C H D B 114 P16.

run line from 1/4 2-11 south to 1/16 corner found as recorded P668.

found stone Mon. (No Orig) which came 124.8 south of center road alignment. Angle this line to road. from S to N.E. 122°05'

- road could not be laid out by this. 1/16 corner still is south of road

Card on center 11 calls that 1/16 lies in erosion gully which may be erronious - if gully in reference is gully north of road this point could be property corner set at some time.

Power Dam Survey 1916 Stone Found

meas. East 2597.6, West 2610.4

Cont'd on next card

Gen'l Notes by M. Karrick 1854

40.00 Set temp. 1/4 section post

West on true line between sections 2 & 11

40.00 Set 1/4 section post N 9° 22' W

Aspen 8 in dia W 255

Jack Oak 7 in dia W 270