9-22-72 set C/N meander corner 270' South.

#890308 ①

1/4 section corner North 1/4 3 Oroville 108-14

12-1895 2r Fraser. P586 No 534. L2 Loco, King., Kurth

Corner usually not set on correction line

- would come N & L - govt record for N line 3 80.15'
- ran S Section lines N 3-4 east to N 1-2
- mile on north line 3 would be 79.58 or 5252.28 actual.
- set long distance at North 2-3 (now under 30' water
- N 1/4 3 now 30' out into lake in lagoon & ever set
  - L> See Oroville Book A, Page 2 and 11)
- 1/16 corner west also in lake, N 2-3 also in lake.
- 1/16 east a C/N set by J Kerr in survey Postiere point.
- now Moved. 13.42 east to set N & L but kept on line as ie.

(over)

9-18-72 set meander corner using line projected from stone, S¼43 found 8-18-72 to be 5.45' west of long wood corner at ¼ 3-10, and point 4.53 east of C/M at Center 3. (a point arrived at by final computation of lines. — ½ between Center 3 and N¼43 set as follows RP on Center 3. set on line and 1322.42 then 1082.17 to meander 1352.17 to RP. Meander corner 270' South of true corner never set

14.3 E.S.E. to punch hole in top center N end 15" cedar.
25.57 E. N E. to 60 D nail on N side 36" oak up 15"
60.15 S.S.E to corner of house siding at SW corner house.
30'± N to lake shore
1535.96 W to C/M meander corner P O T (See N 3-4)
2626.41 W to C/M as N 3-4 section corner.

#840308 (2)

North ¼ Corner 3, Oronoco, 108-14

4-11-83, N¼ Cor 3: Found CIM Meander Corner OK.
Set Survey Marker sign post .45 N and steel
fence post .8 South