1 6-5-1969 found heavy steel with gear & stone, left as is #840407

section corner. North 4-5 Drovers 108-14 Wat Co.

6-1894 2t Fraser P550 No 508 S 5&6 A Pierce
2t Ruber
J&T Hoffman.

found stone & stake - drove iron stake in its place.

-16 west set stone and stake N&L 20.04 5/16
-16 south set stone at 20.30 then 20.02 to 1/4 corner.
-16 center NE 1/4 5 set stone 6x6x18 intern liner.

9-1893 2t Fraser P533 No. 496 S 6 A Sholty-A Gillespie
in setting NE cor 6. ran & meas town line from twp cor
NW cor 6 to NE cor 5 where a "Casting" was found at
NE 5 meas 2 miles only ran 5 links. govt records
18.36 3/8. 20.00 5/8 Ans 6. 40.01 1/4 NW 5 80 S 82 1/2. NE 5

5-28-1969 J Kerr Found corner found Crushed railroad tie type post set in concrete with grader blade brace to south. in line new barb fence. fence east straight & in line had its own corner post just east of R R Tie - latter and a mess of old woven wire around post zoned hot dry and needs watching. Accepted R R tie as corner at this time for line & mark west - west side of post as mean and line of fence east as line. May look for stone south of unable to find 1/4 4-5.

6-5-69 found heavy 1" shaft and cast gear with limestone on west side 12" deep - 3' west and 11' south of corner post of fences - E-W-S. did not set C I M. set track, toy barge, bridge, dirt road etc. - mean south to 1/4 4-5 found 2661.6 - Fence west at 12.96., stone likely 43'+ south. - which is not true fence line common owned. ± mean west to 1/16 stone found 1323.4 - 1/16 stone has 1" pipe just W of stone placed to come over stone to mean center. which lies off road on slope on road curve - 36.6 SW - 30.75 SE to center power poles. - mean west from 1/16 to N 1/4 S as set 13232.

later moved 2.06 E to line fr South

Ornamental section corner north 4-5 #840407 (2)

640:20 80.28 Intersect Standard Parallel No 2
3970 lks. East of 1/4 section post on South
Boundary of sect. 32 in Township 109
Set post for section corner 4-5 Control
mound with trench pits, charred stake
and Osage Orange scribs at each angle

4-19-83, N 4-5: Pulled shaft found here by Ken in
1969 and drove a Telspar pipe with a Cast Iron Cap in
its place. The corner is 3' West and 11' South of the
corner post to fences E-W-S as described by Ken
Top of CIC down .1
RP: Old pipe caps in West side of corner post
NNE 11.85