3-19-76 Set ½" rod on S. side corner post. #841305

section corner 13-14-23-24. Aronoco 108-14.
T.H. field BK 4 p.100-101 1876 - corner lying on ground + both B.T. grubbed out, but King alters corner of fence set at old post - meas 50. 19.72
~~No court house records.~~

8-1929 J Kerr. B2 P14 - 21 - 25
found red cedar post claimed by adjoining land owners as accepted section corner.
- Meas north 1 mile to stone (now C/M) 5265.5
set point M&L to use in line of E-W ¼ line.

This cedar post also used in Power Dam Survey 1916 and is shown on their drawings.

3-19-76 Set ½" x 15" rod (up 4") on S. side of corner post to fences N-E-W. Corner 66' E of pasture fence S.
R.P.'s: CSD E side of power pole S. 30.06
Spike + CSD S. side 8" Box Elder ESE 8.40

Power Dam survey (1916) used Cedar post as corner

Gov't Meters Mt. [illegible] 1854

80.00 Set post for [illegible] to Set

13-14-23-24

Bar Oak 10 N 53 W 295

" " 7 S 22 E 370

Dug trench

8/17/93 Fd 5/8" Iron set in 1976 on So. Edge C.P. to fence E-W-N in good condition. Nailed survey sight to Corner Post and set steel Post south of corner.